



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 8602E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (SN)	DEFORMED	2,560.00	2,560.00
1	FRONT BUMPER FIXING PARTS (SN)	NOT NECESSARY	259.00	-
1	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE (SN)	CRACKED	228.00	227.50
1	FRONT BUMPER GRILLE-LOWER CENTRE (SN)	CRACKED	135.00	135.00
1	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE (SN)	NOT NECESSARY	194.00	-
1	FRONT BUMPER SUPPORT ELEMENT-UPPER (SN)	NOT NECESSARY	59.00	-
1	RADIATOR GRILLE (SN)	CRACKED	1,090.00	1,090.00
1	FRONT AIR GUIDE GRILLE-LH (SN)	CRACKED	135.00	135.00
1	FRONT WHEEL SPOILER-LH (SN)	NOT NECESSARY	51.00	-
1	FRONT BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	926.00	-
1	FRONT FOAM FILLER PIECE (SN)	CRACKED	124.00	124.00
2	FRONT BUMPER REINFORCEMENT BEAM SUPPORT-LH/RH (SN)	NOT NECESSARY	26.00	-
1	FRONT BUMPER GUIDE SECTION-LH (SN)	NOT NECESSARY	36.00	-
1	FRONT BUMPER COVER (SN)	CRACKED	127.00	127.00
1	STICKER FOR SIGN "CAUTION" (SN)	NECESSARY	14.00	13.60
1	STICKER FOR AIR CONDITIONER (SN)	NECESSARY	30.00	30.00
1	SIGNAL HORN-LH (SN)	NOT NECESSARY	201.00	-
1	SIGNAL HORN SPRING SHACKLE-LH (SN)	NOT NECESSARY	25.00	-
1	FRONT FENDER-LH (SN)	BUCKLED	990.00	990.00
1	FRONT FENDER ATTACHMENT PARTS (SN)	NOT NECESSARY	57.00	-
1	FRONT FENDER BRACKET-LH (SN)	NOT NECESSARY	53.00	-
1	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH (SN)	NOT NECESSARY	49.00	-
1	FRONT FENDER BRACE-LH (SN)	NOT NECESSARY	118.00	-
1	FRONT WHEEL HOUSING LINER-LH (SN)	NOT NECESSARY	240.00	-
1	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (SN)	NOT NECESSARY	45.00	-
1	FRONT STONE CHIP GUARD (SN)	NOT NECESSARY	73.00	-
1	ADHESIVE TAPE (SN)	NOT NECESSARY	55.00	-

Report Ref No. CS/CTI21006780/Atcn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET (SN)	TO REPAIR SEE LABOUR	3,241.00	-
1	BONNET PROTECTIVE FILM (SN)	NOT NECESSARY	46.00	-
2	BONNET LID HINGE-LH/RH (SN)	NOT NECESSARY	148.00	-
1	BONNET CATCH HOOK (SN)	NOT NECESSARY	140.00	-
1	BONNET EDGE PROTECTION (SN)	NOT NECESSARY	28.00	-
1	BONNET LID LOCK WITH MICRO SWITCH (SN)	NOT NECESSARY	214.00	-
1	BONNET LOCK COVER (SN)	NOT NECESSARY	23.00	-
1	HEADLIGHT MOUNTING-LH (SN)	CRACKED	118.00	118.00
1	HEADLIGHT BRACKET-LH (SN)	NOT NECESSARY	106.00	-
1	HEADLIGHT LH (SN)	NOT NECESSARY	2,343.00	-
1	FRONT FOG LAMP-LH (SN)	NOT NECESSARY	262.00	-
1	HEADLIGHT LIFT CYLINDER-LH (SN)	NOT NECESSARY	210.00	-
1	HOSE FOR HEADLIGHT WASHER SYSTEM (SN)	NOT NECESSARY	182.00	-
1	FRONT LOCK CARRIER (SN)	NOT NECESSARY	1,016.00	-
1	FRONT LOCK CARRIER BRACKET-LH (SN)	NOT NECESSARY	45.00	-
1	TEMPERATURE SENSOR BRACKET-LH (SN)	NOT NECESSARY	19.00	-
6	COOLANT FOR RADIATOR (SN)	NOT NECESSARY	142.00	-
1	RADIATOR AIR GUIDE-LH (SN)	NOT NECESSARY	27.00	-
1	FRONT NO PLATE (SN)	NECESSARY	60.00	60.00
1	SUNDRIES (SN)	NECESSARY	300.00	9.20
			16,570.00	5,619.30
	LABOUR			
	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY.		360.00	360.00
	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.		350.00	350.00
	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR.RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS.	NOT NECESSARY	1,200.00	-

Report Ref No. CS/CTI21006780/Atcn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,LHS FRONT FENDER AND LHS HEADLIGHT,RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.TO REPAIR BOTH FRONT FENDER TOP SUPPORTS.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL PARTS REMOVED.		4,900.00	1,400.00
	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,HINGES AND BONNET.		3,000.00	2,100.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			10,002.00	4,402.00
GRAND TOTAL			26,572.00	10,021.30
RECOMMENDED COST OF REPAIRS				10,021.30

Report Ref No. CS/CTI21006780/Atcn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.