

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006782/TVCN2**Date:** 14/02/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00052682100		
Claimant Vehicle No :	SLZ8869D	Insured Vehicle No :	YP800C		
Date of Loss:	11/06/2021	Nature of Claim:	TP	Claim No:	SNM21D203365/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ8869D		Engine No:	65492080095385
Make & Model:	MERCEDES-BENZ E220D SE, 2.0 (A)		Chassis No:	WDD2130132A235923
Reg. Date:	29/09/2017 (Man. Year: 2017)		Odometer:	36553 km
Colour:	Black			
Engine Capacity:	1950 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,075.20	6,024.90	8,050.30	57.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.00	2,240.00	4,100.00	64.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,415.20	8,264.90	12,150.30	59.52
Approved Total (Overridden) (\$\$)		6,600.00		
(\$\$)	20,415.20	6,600.00	13,815.20	67.67
+ GST 7.00/7.00% (\$\$)	1,429.06	462.00	967.06	67.67
Nett Amount (\$\$)	21,844.26	7,062.00	14,782.26	67.67

INSPECTION

Date of Assignment:	17/06/2021	
Date Inspected:	18/06/2021	Inspected At: AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2022)
Parts: 143	MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ8869D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP LH	Cut	894.00 FL	*894.00 FL
2	1		*TAIL LAMP LOWER BRACKET LH	Cracked	370.00 FL	*370.00 FL
3	1		*REAR BUMPER	Deformed	1,670.00 FL	*1,670.00 FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	370.00 FL	*- FL
5	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	255.00 FL	*255.00 FL
6	1		*REAR BUMPER LOWER	Not Necessary	478.00 FL	*- FL
7	1		*REAR BUMPER LOWER CHROME	Not Necessary	388.00 FL	*- FL
8	1		*REAR BUMPER RETAINER LH	Necessary	126.00 FL	*126.00 FL
9	1		*REAR BUMPER CENTER BRACKET	Not Necessary	105.00 FL	*- FL
10	1		*REAR BUMPER CARRIER	Not Necessary	769.00 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT BAR (NPA)	Not Necessary	-	*- FL
12	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR BUMPER UNDERCOVER (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*REAR WINDSCREEN MOULDING	Necessary	254.00 FL	*254.00 FL
15	1		*REAR FENDER LH	Bent	1,600.00 FL	*1,600.00 FL
16	1		*REAR FENDER COWLING LH	Torn	342.00 FL	*342.00 FL
17	1		*REAR WHEELHOUSE LH (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*REAR DOOR LH	Repair	2,337.96 FL	*- FL
19	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	305.97 FL	*- FL
20	1		*REAR ABSORBER LH	Not Necessary	565.00 FL	*- FL
21	1		*REAR UPPER ARM LH (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*REAR LOWER ARM LH	Not Necessary	715.43 FL	*- FL
23	1		*REAR CONTROL ARM LH (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*REAR STRAIGHT ARM LH (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*REAR KNUCKLE ARM LH	Not Necessary	1,488.20 FL	*- FL
26	1		*REAR KNUCKLE BEARING LH (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*REAR BEARING HUB LH (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*REAR RIM LH	Cut	1,050.00 FL	*1,050.00 FL
29	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*10.00 FS
30	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
31	1		*REAR FENDER SEALANT	Necessary	200.00 FS	*60.00 FS
32	1		*REAR FENDER COWLING LH	Necessary	100.00 FS	*20.00 FS
33	1		*REAR WHEELHOUSE SEALANT	Not Necessary	150.00 FS	*- FS
34	1		*REAR TYRE LH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,483.56	6,681.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,408.36	656.10
Total Parts (\$\$)	14,075.20	6,024.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	800.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	750.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
8	TO RNR UNDERCARRIAGE	New	300.00	0.00
9	TO CHECK WHEEL BALANCING	New	250.00	30.00
10	TO CHECK WATER LEAK	New	150.00	30.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	1,200.00	280.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
13	TO PERFORM RUST PROOFING	New	400.00	30.00
14	TO RNR REAR DOOR MECHANISM	New	40.00	0.00
			Gross Labour Cost (S\$)	6,340.00
				2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >