



# TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation  
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10060/8028/TP/12.21

Date : 08 December 2021

Vehicle no : SLR 8028G

To: Simon Chin Fen Yoo  
c/o 2 Kaki Bukit Ave 2  
#01-36, Kaki Bukit Autohub  
Singapore 417921

## VEHICLE INSPECTION REPORT

Name of Workshop : Sheng Li Lai  
Place of inspection : 2 Kaki Bukit Ave 2 #01-36, Kaki Bukit Autohub, Singapore 417921  
Date of Accident : 03 December 2021  
Date of Inspection : 06 December 2021

### VEHICLE PARTICULAR

Registration No.	: SLR 8028G	Chassis Frame No.	: ACR50-0040560
Make / Model	: Toyota Estima 2.4A	Engine No.	: 2AZF043265
Year of Registration	: 2007	Odometer Reading	: 229,947 KM
Class / Type	: MPV	Colour	: Silver

### VEHICLE CONDITION

General Condition	: Good	Steering	: Serviceable
Paintwork	: Good	Foot/ Parking Brake	: Serviceable

### TYRE CONDITION

	<u>Size</u>	<u>Thread Balance</u>
Front L/H :	ARIVO 215 / 60 R16	8mm
Front R/H :	ARIVO 215 / 60 R16	8mm
Rear L/H :	ARIVO 215 / 60 R16	8mm
Rear R/H :	ARIVO 215 / 60 R16	8mm

\* The above is an estimate of the remaining life of the tyre thread in percentages

### COST OF REPAIR

	Repairer S\$	Adjuster S\$
Parts	\$ 10,053.80	\$ 7,074.85
Labour	\$ 3,680.00	\$ 3,090.00
	<u>\$ 13,733.80</u>	<u>\$ 10,164.85</u>

### TY5 Recommendation

Lump Sum Repair :  
\$ 8,150.00

Estimated Repair Duration :

7

working days (excluding Sat, Sun & Public Holidays)

NOTE : The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



# TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

Our Services : Automotive Surveying | Vehicle Valuation  
Motor Claims Investigation | Evaluation & Consultation

Reference : TY5/TA/10060/8028/TP/12.21  
Date : 08 December 2021  
Vehicle no : SLR 8028G

## ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>	
<b><u>LIST ITEMS:-</u></b>						
1	1 pc	rear bumper ✓	deformed	\$ 1,210.00	\$ 1,210.00	715
2	2 pcs	rear bumper side retainer @\$79.00 ✓	necessary	\$ 158.00	\$ 158.00	139.6
3	2 pcs	rear bumper side support @\$61.00 X SVC	necessary	\$ 122.00	\$ 122.00	X
4	2 pcs	rear bumper reflector @\$65.90 ✓	broken	\$ 131.80	\$ 131.80	107.4
5	1 set	rear bumper clips ✓	necessary	\$ 35.00	\$ 35.00	18
6	1 pc	tailgate ✓	buckled	\$ 1,492.00	\$ 1,492.00	1359.05
7	1 pc	tailgate inner lock ✓	jammed	\$ 409.00	\$ 409.00	359.05
8	1 pc	tailgate chrome garnish ✓	cracked	\$ 381.00	\$ 381.00	214.3
9	1 pc	tailgate logo emblem ✓	necessary	\$ 42.00	\$ 42.00	✓
10	1 pc	tailgate "estima" emblem ✓	necessary	\$ 39.00	\$ 39.00	✓
11	1 pc	tailgate "x" emblem ✓	necessary	\$ 25.00	\$ 25.00	✓
12	1 pc	tailgate l/h side lamp ✓	broken	\$ 292.00	\$ 292.00	✓
13	1 pc	tailgate r/h side lamp ✓	broken	\$ 292.00	\$ 292.00	✓
14	1 pc	tailgate inner ctr trim board ✓	broken	\$ 453.00	\$ 453.00	✓
15	1 set	tailgate inner ctr trim board clips ✓	necessary	\$ 35.00	\$ 35.00	✓
16	1 pc	tailgate weatherstrip ✓	deformed	\$ 329.00	\$ 329.00	✓
17	1 pc	rear windscreen moulding ✓	necessary	\$ 91.00	\$ 91.00	✓
18	1 pc	rear boot opening sensor X SVC	not working	\$ 156.00	\$ 156.00	X
19	1 pc	rear end panel assy - complete ✓	buckled	\$ 880.00	\$ 880.00	629.5
20	1 pc	rear end panel garnish ✓	broken	\$ 457.00	\$ 457.00	294
21	1 pc	spare tyre panel	buckled	\$ 709.00	repair	
22	1 pc	l/h rear fender inner trim board ✓	deformed	\$ 825.00	\$ 825.00	658
23	1 pc	r/h rear fender inner trim board ✓	deformed	\$ 825.00	\$ 825.00	658
				\$ 9,388.80	\$ 8,679.80	6749.9
Less 25%					\$ 2,169.95	
				\$ 9,388.80	\$ 6,509.85	5062.42
<b><u>SPECIAL NETT ITEMS:-</u></b>						
24	1 set	reverse sensor ✓	broken	\$ 300.00	\$ 250.00	200
25	1 pc	rear no. plate ✓	damaged	\$ 60.00	\$ 50.00	25
26	1 pc	rear no. plate frame ✓	deformed	\$ 35.00	\$ 35.00	15
27	1 roll	rear windscreen sealant ✓	necessary	\$ 60.00	\$ 40.00	✓
28	1 roll	rear end panel sealant ✓	necessary	\$ 60.00	\$ 40.00	✓
29	1 set	spare tyre panel insulation pad X SVC	necessary	\$ 150.00	\$ 150.00	X
				\$ 665.00	\$ 565.00	320
<b>Total</b>				\$ 10,053.80	\$ 7,074.85	



# TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation  
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10060/8028/TP/12.21

Date : 08 December 2021

Vehicle no : SLR 8028G

## ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>	
		B/F		\$ 10,053.80	\$ 7,074.85	
30		To panel beat and renewal of all necessary damaged body parts		\$ 1,600.00	\$ 1,400.00	800
31		To check wiring and rewire		\$ 60.00	\$ 50.00	30
32		To remove and reinstall tailgate components		\$ 80.00	\$ 60.00	✓
33		To remove and reinstall rear boot upholstery		\$ 100.00	\$ 80.00	✓
34		To remove and reinstall rear windscreen		\$ 250.00	\$ 200.00	120
35		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00	40
36		To remove and reinstall reverse camera		\$ 150.00	\$ 120.00	40
37		To apply anti-rust		\$ 100.00	\$ 80.00	✓
38		To putty and spray-paint of affected areas		\$ 1,200.00	\$ 1,000.00	800
				\$ 3,680.00	\$ 3,090.00	2050

7432.42

-20%: 5950

6 DAYS

Total \$ 13,733.80 \$ 10,164.85



# TY5 CONSULTANCY

( Registration No.: 53429875C )

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation  
Motor Claims Investigation | Evaluation & Consultation*


Reference : TY5/TA/10060/8028/TP/12.21

Date : 08 December 2021

Vehicle no : SLR 8028G

## ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact of the collision was delivered Squarely to the Rear portion of the vehicle.



( Please refer to the list and survey photographs as attached for more information )

## ASSESSMENT RECOMMENDATIONS

### COST OF REPAIR

	Repaire S\$	Adjuster S\$
Parts	\$ 10,053.80	\$ 7,074.85
Labour	\$ 3,680.00	\$ 3,090.00
	<u>\$ 13,733.80</u>	<u>\$ 10,164.85</u>

### TY5 Recommendation

Contract Lump Sum of \$ 8,150.00

Estimated Repair Duration : 7 working days  
( excluding Sat, Sun & Public Holidays )

Enclosed No. Of Photograph : 96  
(at the time of static inspection )

Our attached assessment schedule has been checked throughly by us against the actual damages sustained on the vehicle, and we recommend the replacement of parts and repair accordingly. We have adjusted the cost and the repaire has agreed to undertake the repair at the recommended sum to a acceptable quality and standards. We have not given authorization and instruction to the repaire to proceed with the repairs.

The survey was done on a **Without Prejudice Basis** and we are reverting the matter to you for a decision.

We thank you for engaging our services and we enclosed herewith our invoice no. 10060

TY5 CONSULTANCY

-----  
TERRENCE HONG  
AUTOMOTIVE SURVEYOR

NOTE : *This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company via email only and follow up with a phone call, within Fourteen ( 14 ) days from the date hereof. Otherwise this revised amount shall be treated as valid.*