

ASS. REC. BY: Tanjah

REF: CS/CT12/006782/TIVC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$135K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: EF Vehicle: IN / OUT

Veh No: SLZ8869D Yr Regn: 2017, Sep.

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E200 c.c 1950.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 36553 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD21301320235923

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R: 2 - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 18/6/21 24hrs

Survey held at AP Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear, u/c.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Estimate not complete.</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
S + RS. SI	
Photos	
Others	

- Add Fee:
- : Site Insp (\$)
 - : Interview (\$)
 - : Tech. Invs (\$)
 - : Weekend (\$)

Report Format: _____
Lump Sum / L.S. (\$) _____



AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date _____
 Vehicle SLZ 8869 D
 Make/Model MERCEDES E200
 Chassis No. WDD2130132A235923

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAIL LAMP LH	1		\$ 894 -
2	TAIL LAMP LOWER BRACKET LH	1		\$ 370 -
3	REAR BUMPER	1		\$ 1670 -
4	REAR BUMPER REFLECTOR LH	1		\$ 370 -
5	REAR BUMPER REVERSE SENSOR SET	1	255	\$ 255 -
6	REAR BUMPER LOWER	1		\$ 2485 478 -
7	REAR BUMPER LOWER CHROME	1		\$ 388 -
8	REAR BUMPER RETAINER LH	1		\$ 126 -
9	REAR BUMPER CENTER BRACKET	1		\$ 105 -
10	REAR BUMPER CARRIER	1		\$ 769 -
11	REAR BUMPER REINFORCEMENT BAR	1		\$ -
12	REAR BUMPER SPONGE	1		\$ -
13	REAR BUMPER UNDERCOVER	1		\$ -
14	REAR WINDSCREEN MOULDING	1		\$ 254 -
15	REAR FENDER LH	1		\$ 1600 -
16	REAR FENDER COWLING LH	1		\$ 342 -
17	REAR WHEELHOUSE LH	1		\$ -
18	REAR DOOR LH	1		\$ 2337.96 -
19	REAR DOOR WEATHERSTRIP LH	1		\$ 305.97 -
20	REAR ABSORBER LH	1		\$ 565 -
21	REAR UPPER ARM LH	1		\$ -
22	REAR LOWER ARM LH	1		\$ 715.43 -
23	REAR CONTROL ARM LH	1		\$ -
24	REAR STRAIGHT ARM LH	1		\$ -
25	REAR KNUCKLE ARM LH	1		\$ 1488.20 -
26	REAR KNUCKLE BEARING LH	1		\$ -
27	REAR BEARING HUB LH	1		\$ -
28	REAR RIM LH	1		\$ 1050 -
			Total	\$ -
			Less 10%	\$ 4961 -
			Total	\$ 4464.90

S/Nett Items				
1	TAIL LAMP CLIPS	10 pcs	50	\$ 50.00
2	REAR BUMPER CLIPS	30 pcs	100	\$ 100.00
3	REAR FENDER SEALANT	60 pcs	200	\$ 200.00

4	REAR FENDER COWLING LH	20	1	100	\$	100.00
5	REAR WHEELHOUSE SEALANT	X N1	1	150	\$	150.00
6	REAR TYRE LH	X N1	1	800	\$	800.00
				Total	\$	1,400.00

120

LABOUR						
1	PANEL BEATING ON AFFECTED AREAS		1	1400	\$	1000 1,400.00
2	SPRAY PAINT ON AFFECTED AREAS		1	1000	\$	750 1,000.00
3	TO RNR REAR WINDSCREEN		1	400	\$	120 400.00
4	TO RNR REAR EXHAUST		1	250	\$	X N1 250.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION		1	150	\$	30 150.00
6	TO RNR REAR INNER TRIM AND UPHOISTERY		1	400	\$	60 400.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST		1	250	\$	80 250.00
8	TO RNR UNDERCARRIAGE		1	300	\$	150? photo 300.00 X N1
9	TO CHECK WHEEL BALANCING		1	250	\$	30 250.00
10	TO CHECK WATER LEAK		1	150	\$	30 150.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS		1	1200	\$	280 280 1,200.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION		1	150	\$	20 150.00
13	TO PERFORM RUST PROOFING		1	400	\$	30 400.00
14	TO RNR REAR DOOR MECHANISM		1		\$	X 40 X N1
						2440
				Total Labour	\$	6,300.00
				Parts Replacement Amount	\$	1,400.00
				Total Amount	\$	7,700.00

Tanf'ik 97495749
 - WP' 18/6/21 @ 4pm
 1/2s Body after repair
 Tanf'ik 1/11/2021
 6 days

4464.90
 120
 2440
 7024.90
 1/2s \$5600 #
 Galys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: