



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2295Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR NUMBER PLATE BRACKET (CONSISTENT)	BENT	74.90	74.90
1	REAR NUMBER PLATE LAMP (CONSISTENT)	NOT NECESSARY	79.80	-
2	TAILLAMP @\$226.20 (CONSISTENT)	NOT NECESSARY	452.40	-
	LESS 25% DISCOUNT		-	-18.73
			607.10	56.17
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	30.00	30.00
1	REAR HORIZONTAL STEP WOODEN PLANK (SN) (CONSISTENT)	CRACKED	380.00	250.00
2	REAR CHASSIS WOODEN PLANK @\$1000.00 (SN) (CONSISTENT)	O/S CRACKED	2,000.00	800.00
1	REAR UPPER WOODEN CROSS MEMBER (SN) (CONSISTENT)	NOT NECESSARY	800.00	-
2	REAR DOOR LOCK BAR @\$280.00 (SN) (CONSISTENT)	NOT NECESSARY	560.00	-
			3,770.00	1,080.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING.	NOT NECESSARY	500.00	-
	WIRING.		50.00	30.00
	TO VARNISH WOODEN PLANK.		200.00	150.00
	TO REMOVE REAR CONTAINER BOX.		400.00	200.00
			1,950.00	780.00
GRAND TOTAL			6,327.10	1,916.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/ASM21006783/Aqce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.