

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006790/TPA3Q2**Date:** 10/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100432181
Claimant Vehicle No :	SKV5607X	Insured Vehicle No :	SKJ845X
Date of Loss:	14/06/2021	Nature of Claim:	TP
		Claim No:	3744352259SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV5607X		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)	Engine No:	4A910049462
Reg. Date:	03/10/2007 (Man. Year: 2007)	Chassis No:	JMYSRCY2A8U000736
Colour:	Red	Odometer:	134802 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,802.50	12,244.90	36,557.60	74.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,150.00	3,070.00	9,080.00	74.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	60,952.50	15,314.90	45,637.60	74.87
Approved Total (Overridden) (\$\$)		7,200.00		
(\$\$)	60,952.50	7,200.00	53,752.50	88.19
+ GST 7.00/7.00% (\$\$)	4,266.68	504.00	3,762.68	88.19
Nett Amount (\$\$)	65,219.18	7,704.00	57,515.18	88.19
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (\$\$)		749.00		
(\$\$)		8,453.00		
Liabile Amount (50.00%) (\$\$)		4,226.50		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		150.00		
Nett Liability (\$\$)		4,383.95		
Global Sum Settlement (\$\$)		4,180.00		

INSPECTION

Date of Assignment:	17/06/2021	
Date Inspected:	17/06/2021	Inspected At: AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BONNET HINGE L+R (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*HEADLAMP L+R	N/S Cut / O/S Not Necessary	1,584.00 FL	*792.00 FL
3	1		*FRONT BUMPER	Deformed	858.00 FL	*858.00 FL
4	1		*FRONT BUMPER FOG LAMP GRILLE L+R	N/S Cut / O/S Not Necessary	60.00 FL	*30.00 FL
5	1		*FRONT BUMPER TOP MOULDING	Not Necessary	30.00 FL	*- FL
6	1		*FRONT BUMPER RETAINER L+R	N/S Necessary/O/SNot Necessary	40.00 FL	*20.00 FL
7	1		*FRONT FENDER INNER PANEL LH	Repair	907.00 FL	*- FL
8	1		*FRONT FENDER COWLING L+R	N/S Torn / O/S Not Necessary	206.00 FL	*103.00 FL
9	1		*FRONT FENDER QUARTER GARNISH L+R	N/S Cut / O/S Not Necessary	52.00 FL	*26.00 FL
10	1		*FRONT SUPPORT PANEL	Not Necessary	520.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	63.00 FL	*- FL
12	1		*FRONT DOOR LH	Bent	900.00 FL	*900.00 FL
13	1		*FRONT DOOR SIDE MIRROR ASSY LH	Cracked	388.00 FL	*388.00 FL
14	1		*FRONT DOOR HANDLE LH	Cracked	70.00 FL	*70.00 FL
15	1		*FRONT DOOR HANDLE END CAP LH	Cracked	14.00 FL	*14.00 FL
16	1		*FRONT DOOR STICKER LH	Necessary	28.00 FL	*28.00 FL
17	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	106.00 FL	*- FL
18	1		*FRONT DOOR INNER WINDOW MOULDING LH	Not Necessary	48.00 FL	*- FL
19	1		*FRONT DOOR INNER BOARD LH	Not Necessary	520.00 FL	*- FL
20	1		*FRONT DOOR LOCK LH	Not Necessary	282.00 FL	*- FL
21	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	16.00 FL	*- FL
22	1		*FRONT DOOR HINGE SET LH	Not Necessary	37.00 FL	*- FL
23	1		*FRONT DOOR CHECKER LH	Not Necessary	28.00 FL	*- FL
24	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	403.00 FL	*- FL
25	1		*FRONT DOOR WINDOW REGULATOR LH	Not Necessary	131.00 FL	*- FL
26	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	129.00 FL	*129.00 FL
27	1		*FRONT DOOR INNER WEATHERSTRIP LH	Necessary	127.00 FL	*127.00 FL
28	1		*B PILLAR LH	Not Necessary	517.00 FL	*- FL
29	1		*B PILLAR INNER TRIM TOP LH	Not Necessary	85.00 FL	*- FL
30	1		*B PILLAR INNER TRIM LOWER LH	Not Necessary	115.00 FL	*- FL
31	1		*ROCKER PANEL LH	Not Necessary	597.00 FL	*- FL
32	1		*SIDE SKIRT LH	Cracked	844.00 FL	*844.00 FL
33	1		*REAR DOOR LH	Bent	1,008.00 FL	*1,008.00 FL
34	1		*REAR DOOR HANDLE LH	Not Necessary	70.00 FL	*- FL
35	1		*REAR DOOR HANDLE END CAP LH	Not Necessary	14.00 FL	*- FL
36	1		*REAR DOOR STICKER LH	Necessary	28.00 FL	*28.00 FL
37	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	106.00 FL	*- FL
38	1		*REAR DOOR INNER WINDOW MOULDING LH	Not Necessary	48.00 FL	*- FL
39	1		*REAR DOOR INNER BOARD LH	Not Necessary	520.00 FL	*- FL
40	1		*REAR DOOR LOCK LH	Not Necessary	282.00 FL	*- FL
41	1		*REAR DOOR LOCK CATCH LH	Not Necessary	16.00 FL	*- FL
42	1		*REAR DOOR HINGE SET LH	Not Necessary	37.00 FL	*- FL
43	1		*REAR DOOR CHECKER LH	Not Necessary	28.00 FL	*- FL
44	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	403.00 FL	*- FL
45	1		*REAR DOOR WINDOW REGULATOR LH	Not Necessary	131.00 FL	*- FL
46	1		*REAR DOOR WEATHERSTRIP LH	Necessary	129.00 FL	*129.00 FL
47	1		*REAR DOOR INNER WEATHERSTRIP LH	Necessary	127.00 FL	*127.00 FL
48	1		*REAR FENDER LH	Repair	898.00 FL	*- FL
49	1		*REAR FENDER INNER PANEL LH	Repair	387.00 FL	*- FL
50	1		*REAR FENDER COWLING LH	Missing	103.00 FL	*103.00 FL
51	1		*REAR FENDER INNER TRIM LH	Not Necessary	223.00 FL	*- FL
52	1		*REAR WHEELHOUSE LH	Not Necessary	223.00 FL	*- FL
53	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
54	1		*BOOTLID	Not Necessary	1,339.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*BOOTLID LAMP LH	Not Necessary	289.00 FL	*- FL
56	1		*TAIL LAMP L+R	N/S Cracked / O/S Not Necessary	664.00 FL	*332.00 FL
57	1		*REAR BUMPER	Deformed	1,205.00 FL	*1,205.00 FL
58	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	20.00 FL	*- FL
59	1		*REAR BUMPER RETAINER L+R	N/S Deformed / O/S Not Necessary	40.00 FL	*20.00 FL
60	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	210.00 FL	*- FL
61	1		*END PANEL	Not Necessary	506.00 FL	*- FL
62	1		*END PANEL TOP GARNISH	Not Necessary	149.00 FL	*- FL
63	1		*FRONT ABSORBER LH	Not Necessary	401.00 FL	*- FL
64	1		*FRONT LOWER ARM LH	Not Necessary	292.00 FL	*- FL
65	1		*FRONT KNUCKLE LH	Not Necessary	321.00 FL	*- FL
66	1		*FRONT KNUCKLE BEARING LH	Not Necessary	143.00 FL	*- FL
67	1		*FRONT BEARING HUB LH	Not Necessary	204.00 FL	*- FL
68	1		*FRONT DRIVE SHAFT LH	Not Necessary	1,114.00 FL	*- FL
69	1		*FRONT TIE ROD LH	Not Necessary	125.00 FL	*- FL
70	1		*FRONT TIE ROD END LH	Not Necessary	53.00 FL	*- FL
71	1		*FRONT STABILIZER BAR	Not Necessary	260.00 FL	*- FL
72	1		*FRONT STABILIZER LINK LH	Not Necessary	123.00 FL	*- FL
73	1		*FRONT CROSSMEMBER	Not Necessary	951.00 FL	*- FL
74	1		*REAR ABSORBER LH	Bent	401.00 FL	*401.00 FL
75	1		*REAR LOWER ARM LH	Bent	136.00 FL	*136.00 FL
76	1		*REAR STRAIGHT ARM LH (NPA)	Not Necessary	0.00 FL	*- FL
77	1		*REAR CONTROL ARM LH (NPA)	Not Necessary	0.00 FL	*- FL
78	1		*REAR KNUCKLE CONTROL ARM LH	Bent	470.00 FL	*470.00 FL
79	1		*REAR KNUCKLE ARM LH (NPA)	Not Necessary	0.00 FL	*- FL
80	1		*REAR KNUCKLE BEARING WITH HUB LH (NPA)	Bent	423.00 FL	*423.00 FL
81	1		*REAR CROSSMEMBER	Not Necessary	1,100.00 FL	*- FL
82	2		*REAR CHASSIS L+R(NPA)	Not Necessary	0.00 FL	*- FL
83	1		*BONNET	Not Necessary	4,000.00 FS	*- FS
84	1		*FRONT GRILLE ASSY	Not Necessary	1,000.00 FS	*- FS
85	1		*FRONT LOGO-MITSUBISHI	Not Necessary	300.00 FS	*- FS
86	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
87	1		*SET FRONT BUMPER FOG LAMP GARNISH	Cut	800.00 FS	*200.00 FS
88	1		*FRONT NUMBER PLATE	Cut	200.00 FS	*45.00 FS
89	1		*FRONT FENDER LH	Cracked	3,500.00 FS	*1,200.00 FS
90	1		*FRONT FENDER SIDE GARNISH LH	Cracked	400.00 FS	*150.00 FS
91	1		*FRONT FENDER SIGNAL LAMP LH	Cracked	250.00 FS	*100.00 FS
92	1		*FRONT FENDER CLIPS	Necessary	100.00 FS	*30.00 FS
93	1		*FRONT FENDER INNER PANEL SEALANT	Not Necessary	150.00 FS	*- FS
94	1		*FRONT FENDER COWLING CLIPS	Necessary	150.00 FS	*20.00 FS
95	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
96	1		*SET FRONT DOOR SIDE MIRROR COVER	Cracked	800.00 FS	*250.00 FS
97	1		*FRONT DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
98	1		*SET FRONT DOOR VISOR	Necessary	400.00 FS	*150.00 FS
99	1		*REAR DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
100	1		*SET REAR DOOR VISOR	Necessary	400.00 FS	*150.00 FS
101	1		*B PILLAR SEALANT	Not Necessary	150.00 FS	*- FS
102	1		*B PILLAR INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
103	1		*ROCKER PANEL SEALANT	Not Necessary	150.00 FS	*- FS
104	1		*SIDE SKIRT CLIPS	Necessary	150.00 FS	*30.00 FS
105	1		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
106	1		*REAR FENDER SEALANT	Not Necessary	200.00 FS	*- FS
107	1		*REAR FENDER COWLING CLIPS	Necessary	150.00 FS	*20.00 FS
108	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
109	1		*REAR WHEELHOUSE SEALANT	Not Necessary	150.00 FS	*- FS
110	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
111	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

3/10/23, 11:19 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
112	1		*END PANEL SEALANT	Not Necessary	220.00 FS	*- FS
113	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
114	2		*SET FRONT RIM	Dented (1 PCS ONLY)	4,000.00 FS	*800.00 FS
115	2		*SET FRONT TYRE (80%) (\$200.00)	Cut (1 PCS ONLY)	1,600.00 FS	*160.00 FS
116	2		*SET REAR RIM	Bent (1 PCS ONLY)	4,000.00 FS	*800.00 FS
117	2		*SET REAR TYRE (80%) (\$200.00)	Punctured (1 PCS ONLY)	1,600.00 FS	*160.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						51,345.00 13,116.00
- List Item Discount on L Items 10.00/10.00% (\$\$)						2,542.50 871.10
Total Parts (\$\$)						48,802.50 12,244.90
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	4,200.00	1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	New	3,000.00	1,400.00
3	TO RNR REAR WINDSCREEN	New	400.00	0.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
6	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
7	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	New	150.00	0.00
8	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
10	TO RNR UNDERCARRIAGE (FRONT AND REAR)	New	400.00	200.00
11	TO CHECK WHEEL BALANCING	New	250.00	60.00
12	TO CHECK WATER LEAK	New	150.00	20.00
13	TO RNR FUEL TANK	New	250.00	0.00
14	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
15	TO RNR REAR BOOTLID MECHANISM	New	400.00	0.00
16	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
17	TO PERFORM RUST PROOFING	New	400.00	40.00
18	TO RNR REAR AND FRONT DOOR MECHANISM	New	600.00	120.00
Gross Labour Cost (S\$)			12,150.00	3,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >