

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG21006791/R1TF3N2**Date:** 18/11/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001621506
<b>Claimant Vehicle No :</b>	PC9473D	<b>Insured Vehicle No :</b>	SLH5426M
Date of Loss:	11/06/2021	Nature of Claim:	TP
		Claim No:	258548

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>PC9473D</b>	Engine No:	1GD8453593
Make & Model:	TOYOTA HIACE, 2.8 D COMMUTER GL (A)	Chassis No:	GDH2232002288
Reg. Date:	01/10/2020 (Man. Year: 2019)	Odometer:	67530 km
Colour:	Grey		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,428.75	1,256.25	172.50	12.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	540.00	360.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>2,328.75</b>	<b>1,796.25</b>	<b>532.50</b>	<b>22.87</b>

INSPECTION

Date of Assignment:	17/06/2021		
Date Inspected:	22/06/2021	Inspected At:	A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650 Singapore 680113
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2021)
<b>Parts:</b>	213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC9473D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Bent	1,675.00 FL	*1,675.00 FL
2	1		*FRONT DOOR HINGE TOP LH	Serviceable	115.00 FL	*- FL
3	1		*FRONT DOOR HINGE BOTTOM LH	Serviceable	115.00 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>1,905.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>476.25</b>
					<b>Total Parts (\$\$)</b>	<b>1,428.75</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R/R DOOR MECHANISM	New	300.00	250.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	350.00	250.00
3	WIRING CHARGES	New	100.00	0.00
4	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	150.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>900.00</b>	<b>540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >