

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006792/ARA3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900079463
Claimant Vehicle No :	SJM3061S	Insured Vehicle No :	SMH5788G
Date of Loss:	14/06/2021	Nature of Claim:	TP
		Claim No:	7131945490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM3061S	Engine No:	G4FC8U565461
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Chassis No:	KMH DU41BR9U647680
Reg. Date:	27/12/2008 (Man. Year: 2008)	Odometer:	275989 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,869.60	3,952.40	2,917.20	42.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	1,700.00	990.00	36.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,559.60	5,652.40	3,907.20	40.87
Approved Total (Overridden) (S\$)		4,500.00		

Nett Amount (S\$)	9,559.60	4,500.00	5,059.60	52.93
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,207.45		

INSPECTION

Date of Assignment: 17/06/2021

Date Inspected: 17/06/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Black Eagle Auto Pte Ltd (HQ)
 25 KAKI BUKIT ROAD 4, #05-80
 Singapore 417800

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,125.00 FL	*442.00 FL
2	1		*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	105.00 FL	*35.00 FL
3	1		*RHS HEADLAMP	Not Necessary	982.00 FL	*- FL
4	1		*RHS SIDE VIEW MIRROR ASSY COMPLETE	Cracked	652.00 FL	*652.00 FL
5	1		*RHS FRONT SHOCK ABSORBER	Bent	492.00 FL	*349.00 FL
6	1		*RHS FRONT LOWER ARM	Bent	288.00 FL	*288.00 FL
7	1		*RHS FRONT KNUCKLE ARM	Damaged	392.00 FL	*392.00 FL
8	1		*RHS FRONT WHEEL BEARING	Damaged	198.00 FL	*198.00 FL
9	1		*RHS FRONT STABILISER BAR	Not Necessary	142.00 FL	*- FL
10	1		*RHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
11	1		*RHS FRONT FENDER	Distorted	752.00 FL	*437.00 FL
12	1		*RHS FRONT FENDER INNER SPLASH SHIELD	Torn	254.00 FL	*175.00 FL
13	1		*RHS FRONT SPORTS RIM	Cracked	980.00 FS	*450.00 FS
14	2		*SET BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
15	1		*SET RHS FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
16	1		*RHS FRONT TYRE	Punctured	280.00 FL	*180.00 FL
17	1		*RHS DRIVE SHAFT	Bent	1,200.00 FL	*986.00 FL
18	1		*BALL JOINT	Bent	150.00 FL	*77.00 FL
19	1		*TIE ROD END	Bent	200.00 FL	*92.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,312.00	4,813.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,442.40	860.60
Total Parts (\$\$)	6,869.60	3,952.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS ,REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	600.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	750.00	700.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS AND FOCUS HEADLAMP BEAM	New	250.00	30.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	40.00
5	TO CARRY OUT COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	80.00
6	TO REMOVE AND REPLACE RHS FRONT UNDERCARRIAGE PARTS (SUSPENSION SYSTEM)	New	250.00	250.00
Gross Labour Cost (\$\$)			2,690.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >