



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4366U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER BRACKET (CONSISTENT)	BENT	85.00	85.00
1	REAR FENDER (CONSISTENT)	CRACKED	48.00	48.00
1	COVER FENDER (UPPER) (CONSISTENT)	CRACKED	35.00	35.00
1	REAR LICENSE PLATE LIGHT (CONSISTENT)	CUT	60.00	60.00
	LESS 10% DISCOUNT		-	-22.80
			228.00	205.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	20.00	15.00
			20.00	15.00
	<u>LABOUR</u>			
	LABOUR CHARGES.		300.00	200.00
			300.00	200.00
	GRAND TOTAL		548.00	420.20
RECOMMENDED COST OF REPAIRS				420.20

Report Ref No. CC4/ASM21006794/Vps3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.