



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN KHONG			Ref: CC4/ASM21006794/Vps3q2 Date: 02/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJF 5153J	Veh. Inspected	FBS 4366U
	Policy No.	P1741252	Coverage (\$)	0.00
	Claim No.	S1M03BZR	Excess (\$)	0.00
	Assign From		Assign Date	17/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ADV150A	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	KF381008915	Colour	WHITE
	Odometer	1902 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/80 R14	MAXXIS	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70 R13	MAXXIS	7 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/06/2021	Inspection Date	17/06/2021
	Survey held at	25 KAKI BUKIT ROAD 4 #01-24/25 SYNERGY @KB		
	Repairer	UNITED CYCLES LLP		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	