

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006797/T1GS3Q2
Date: 14/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070102705
Claimant Vehicle No :	SHC1054C	Insured Vehicle No :	SMT8810S
Date of Loss:	16/06/2021	Nature of Claim:	TP
		Claim No:	4327455884SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1054C	Engine No:	D4DFU596325
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMHU097724
Reg. Date:	29/12/2016 (Man. Year: 2016)	Odometer:	603664 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,598.72	978.00	620.72	38.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	810.00	120.00	12.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,528.72	1,788.00	740.72	29.29
Approved Total (Overridden) (S\$)		1,450.00		

(S\$)	2,528.72	1,450.00	1,078.72	42.66
+ GST 7.00/7.00% (S\$)	177.01	101.50	75.51	42.66
Nett Amount (S\$)	2,705.73	1,551.50	1,154.23	42.66
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$110.67/day) (S\$)		276.68		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,955.18		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment: 17/06/2021

Date Inspected: 17/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY -RR BUMPER	Deformed	1,106.00 FL	*1,106.00 FL
2	1		*COVER -RR BUMPER LWR	Repair	228.00 FL	*- FL
3	1		*ABSORBER -RR BUMPER ENERGY	Not Necessary	119.50 FL	*- FL
4	1		*BEAM -RR BUMPER	Not Necessary	428.40 FL	*- FL
5	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
6	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
7	1		*REFLECTOR /REFIX ASSY -RR	Cut	32.00 FL	*32.00 FL
					Sub Total (\$\$)	1,985.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	387.18
					Total Parts (\$\$)	1,598.72

978.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	ADVERTISEMENT STICKER -BUMPER	New	50.00	50.00
4	ADVERTISEMENT STICKER -FENDER	New	200.00	200.00
5	REMOVE /REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			930.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >