

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006799/AGS3Q2
Date: 12/11/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005568_01
Claimant Vehicle No :	GBE9770B	Insured Vehicle No :	YM9136T
Date of Loss:	15/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002579

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9770B	Engine No:	4JJ12L9579
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Chassis No:	JAANHR85EG7100131
Reg. Date:	16/05/2016 (Man. Year: 2016)	Odometer:	222970 km
Colour:	White		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13
Front Left Side:	SUNFULL 6 mm	Rear Left Side:	SUNFULL 6 mm
Front Right Side:	SUNFULL 6 mm	Rear Right Side:	SUNFULL 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,104.00	2,155.10	5,948.90	73.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,530.00	1,180.00	43.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,814.00	3,685.10	7,128.90	65.92
Approved Total (Overridden) (S\$)		2,950.00		

	(S\$)	10,814.00	2,950.00	7,864.00	72.72
+ GST 7.00/7.00% (S\$)		756.98	206.50	550.48	72.72
Nett Amount (S\$)		11,570.98	3,156.50	8,414.48	72.72
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/06/2021

Date Inspected: 18/06/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Nov 2021)	
Parts:	N/A	ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9770B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TIPPER LOWER MEMBER	Dented	780.00 FL	*450.00 FL
2	1		*REAR CROSSMEMBER	Not Necessary	800.00 FL	*- FL
3	1		*TAIL GATE PLYWOOD	Cracked	380.00 FS	*120.00 FS
4	1		*REAR TIPPER DOOR	Dented	2,100.00 F	*1,320.00 FN
5	2		*REAR TIPPER SIDE PANEL -LH/RH	Repair	2,400.00 F	*- FN
6	2		*REAR TIPPER RUBBER SUPPORT	Not Necessary	170.00 F	*- FN
7	1		*REAR TIPPER LOCK	Not Necessary	110.00 F	*- FN
8	1		*SET REAR TIPPER SIDE FRAME	Not Necessary	950.00 F	*- FN
9	2		*REAR TIPPER HINGES	Bent	246.00 F	*246.00 FN
10	1		*TAIL LAMP ASSY -RH	Cracked	190.00 F	*190.00 FN
11	1		*70KM/H STICKER	Necessary	40.00 FS	*15.00 FS
12	1		*ISUZU STICKER	Necessary	95.00 FS	*95.00 FS
13	1		*FLAMMABLE STICKER	Necessary	40.00 FS	*20.00 FS
14	1		*NUMBER PLATE	Bent	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,341.00	2,486.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	237.00	67.50
- Nett Item Discount on N Items 0.00/15.00% (\$\$)	0.00	263.40
Total Parts (\$\$)	8,104.00	2,155.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RENEW & REFIX ALL ABOVE PARTS	New	1,200.00	700.00
2	LABOUR TO CONNECT & REWIRE & RENEW TAIL LAMP	New	180.00	30.00
3	TO RUST PROOFING AT ACCIDENT DENTED AREA	New	380.00	100.00
4	TO SPRAY & PAINTING AT ACCIDENT DENTED AREA	New	950.00	700.00
			Gross Labour Cost (\$\$)	1,530.00
			2,710.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >