

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21006809/DVF3E2

**Date:** 29/07/2021

### REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD Policy No: 0999993662

Date of Loss: 03/05/2021

Nature of Claim: OD

Claim No: 9863564270SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2469C	Engine No:	28291480027612
Make & Model:	MERCEDES-BENZ A200, 1.3 (A)	Chassis No:	WDD1770872J037805
Reg. Date:	12/12/2018 (Man. Year: 2018)	Odometer:	38369 km
Colour:	Black		
Engine Capacity:	1332 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,852.95	1,726.40	126.55	6.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	870.00	910.00	51.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,632.95</b>	<b>2,596.40</b>	<b>1,036.55</b>	<b>28.53</b>
<b>- Excess (S\$)</b>	<b>1,700.00</b>	<b>1,700.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>1,932.95</b>	<b>896.40</b>	<b>1,036.55</b>	<b>53.63</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>135.31</b>	<b>62.75</b>	<b>72.56</b>	<b>53.63</b>
<b>Nett Amount (S\$)</b>	<b>2,068.26</b>	<b>959.15</b>	<b>1,109.11</b>	<b>53.63</b>

### INSPECTION

Date of Assignment: 18/06/2021

Date Inspected: 18/06/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** BRYAN TANI

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Dented	880.00 F	*880.00 F
2	1		*REAR BUMPER SIDE RETAINER - RH (WCP)	Serviceable	78.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent/Dented	410.00 F	*410.00 F
4	1		*REAR BUMPER REFLECTOR - RH (WCP)	Mtg Cracked	48.00 F	*48.00 F
5	1		*REAR BUMPER SENSOR (WCP)	Damaged	138.00 F	*138.00 F
6	6		*REAR BUMPER SENSOR SEALS (WCP)	Necessary	48.00 F	*48.00 F
7	1		*REAR BUMPER CLIPS (15PCS)	Necessary	90.75 FS	*50.00 FS
					Sub Total (\$\$)	1,692.75 1,574.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	160.20 152.40
					Total Parts (\$\$)	1,852.95 1,726.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT & REPAIR RH REAR CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	800.00	400.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	40.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	30.00
4	TO PUTTY AND SPRAY ON AFFECTED AREAS	New	800.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,780.00</b>	<b>870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >