

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

Email: willybjt@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Steve Tan Loon Cheong
c/o Goh JP & Wong LLC
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBM6777/0321/tpw
Date : 21 June 2021

REFERENCES

Claim Type	: Third Party	Date of Accident	: 12 March 2021
Vehicle No	: FBM 6777 K	Date of Assignment	: 30 March 2021
Make	: Yamaha	Date of Inspection	: 30 March 2021
Model	: TMAX530(DX)	Date of Re-inspection	: 09 April & 18 June 2021
Registration Date	: 31 January 2018	COE Expiry	: 30 January 2028
Color	: Black	Chassis No	: Blocked
Odometer	: 33,109 miles	Engine No	: J415E022339

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Bridgestone	120/70-15	5mm
Rear	Bridgestone	160/60-15	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at both sides.

Please refer to photographs and assessment of repairs for details

Enclosed (78) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$9,757.94 Revised Assessment \$6,900.00 Lump sum

Survey conducted at Hua Chin (2000) Trading Motor Service Centre

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Six (6) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and on the use of ex-stock reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBM 6777 K

Our Ref: PA/FBM6777/0321/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation	
1	Handle bar	1 pc	Usable	274.50	-	x R
2	Handler bar balancer	1 set	Usable	80.00	-	x R
3	Handle bar starter switch assy	1 pc	Cracked	282.30	282.30	-
4	Mirror @ \$157.90/-	1 set	Grazed/broken	315.80	315.80	-
5	Brake lever LH	1 pc	Bent	78.00	78.00	x nn
6	Front cover	1 pc	Hdr cracked	375.70	375.70	x nn
7	Front cover inner panel	1 pc	Hdr cracked	117.20	117.20	x nn
8	Body cowling RH/LH @ \$313.90/-	2 pcs	Cut	627.80	627.80	-
9	Front headlamp assy	1 pc	Hdr cracked	1,658.30	1,658.30	x nn
10	Front indicator light assy @ \$147.80/-	2 pcs	Grazed LH	295.60	147.80	-
11	Leg shield panel LH/RH @ \$254.10/-	2 pcs	Cut	508.20	508.20	-
12	Body cover panel LH /RH @ \$265.20/-	2 pcs	Cut/deformed	530.40	530.40	-
13	Footrest board LH	1 pc	Cut	357.20	357.20	-
14	Tail board panel LH/RH @ \$292.80/-	2 pcs	Cracked/cut	585.60	585.60	-
				6,086.60	5,584.30	
List price discount-10%				608.66	558.43	
				5,477.94	5,025.87	
<u>Special nett item</u>						
15	Front fork oil seal & dust cover	2 pcs	Necessary	240.00	120.00	x nn
16	Front fork hydraulic fluid	4 lits	Necessary	80.00	40.00	x nn
17	Steering cone & bearing	1 set	Necessary	220.00	110.00	x nn
18	Exhaust muffler assy (Akrapovic)	1 pc	Dented	1,860.00	1,860.00	x Revise
				2,400.00	2,130.00	
<u>Labour charges</u>						
Towing (2 trips)				150.00	120.00	60
Check electrical				80.00	60.00	30
Realign front fork				400.00	300.00	x
Realign fork under bracket				200.00	150.00	x
Realign body frame				550.00	450.00	x
Workmanship				500.00	400.00	-
				1,880.00	1,480.00	
Total parts & labour concluded				9,757.94	8,635.87	
Final lump sum repair adjustment					6,900.00	

3 days

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBM 6777 K**

Cur Ref: PA/FBM6777/0321/tpw

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan