



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 6777K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	TO REPAIR SEE LABOUR	274.50	-
1	SET HANDLER BAR BALANCER	TO REPAIR SEE LABOUR	80.00	-
1	HANDLE BAR STARTER SWITCH ASSY	CRACKED	282.30	282.30
1	SET MIRROR (2PCS) @\$157.90	GRAZED / BROKEN	315.80	315.80
1	BRAKE LEVER LH	NOT NECESSARY	78.00	-
1	FRONT COVER	NOT NECESSARY	375.70	-
1	FRONT COVER INNER PANEL	NOT NECESSARY	117.20	-
2	BODY COWLING RH / LH @\$313.90	CUT	627.80	627.80
1	FRONT HEADLAMP ASSY	NOT NECESSARY	1,658.30	-
2	FRONT INDICATOR LIGHT ASSY @\$147.80	N/S GRAZED	295.60	147.80
2	LEG SHIELD PANEL LH / RH @\$254.10	CUT	508.20	508.20
2	BODY COVER PANEL LH / RH @\$265.20	CUT / DEFORMED	530.40	530.40
1	FOOTREST BOARD LH	CUT	357.20	357.20
2	TAIL BOARD PANEL LH / RH @\$292.80	CRACKED / CUT	585.60	585.60
	LESS 10% DISCOUNT		-608.66	-335.51
			5,477.94	3,019.59
<u>SPECIAL NETT ITEMS</u>				
2	FRONT FORK OIL SEAL & DUST COVER (SN)	NOT NECESSARY	240.00	-
4	LITS FRONT FORK HYDRAULIC FLUID (SN)	NOT NECESSARY	80.00	-
1	SET STEERING CONE & BEARING (SN)	NOT NECESSARY	220.00	-
1	EXHAUST MUFFLER ASSY (AKRAPOVIC) (SN)	REUSE	1,860.00	-
			2,400.00	-
<u>LABOUR</u>				
	TOWING (2 TRIPS).		150.00	60.00
	CHECK ELECTRICAL.		80.00	30.00
	REALIGN FRONT FORK.	NOT NECESSARY	400.00	-
	REALIGN FORK UNDER BRACKET.	NOT NECESSARY	200.00	-
	REALIGN BODY FRAME. INCLUSIVE OF THE REPAIR OF HANDLE BAR AND 1 SET HANDLE BAR BALANCER.	NOT NECESSARY	550.00	-

Report Ref No. CS1/ASM21006813/Eqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WORKMANSHIP.		500.00	400.00
			1,880.00	490.00
GRAND TOTAL			9,757.94	3,509.59
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS1/ASM21006813/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.