

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21006816/Bpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	09/06/2022	
	ATTN:CYNTHIA			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 6213H	Veh. Inspected	ł	PC 5148U	
	Policy No.	P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03BZY	Excess (\$)		0.00	
	Assign From		Assign Date		18/06/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE COMMUTER	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	KDH2230028271	Colour		WHITE	
	Odometer	348035 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	MICHELIN		6 mm	
	L/H Front Tyre	195 R15	MICHELIN		6 mm	
	R/H Rear Tyre	195 R15	MICHELIN		6 mm	
	L/H Rear Tyre	195 R15	MICHELIN		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/06/2021	Inspection Dat	e	18/06/2021	
	Survey held at	TEAM AUTOPRO PTE LTD				
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					