

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006819/KGA3Q2**Date:** 18/07/2022**REFERENCE**

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 7210015613 |
| Claimant Vehicle No : | SLU4132Z | Insured Vehicle No : | SFP3188S |
| Date of Loss: | 16/06/2021 | Nature of Claim: | TP |
| | | Claim No: | 2443518661SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLU4132Z | Engine No: | FY77658 |
| Make & Model: | FORD FOCUS, S/W 1.6 (A) | Chassis No: | WF06XXGCC6FY77658 |
| Reg. Date: | 27/08/2015 (Man. Year: 2015) | Odometer: | 80395 km |
| Colour: | Metallic Pearl White | | |
| Engine Capacity: | 1596 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 225/45 R17 | Rear Tyre Size: | 225/45 R17 |
| Front Left Side: | Falken 8 mm | Rear Left Side: | Falken 8 mm |
| Front Right Side: | Falken 8 mm | Rear Right Side: | Falken 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 12,904.70 | 2,903.20 | 10,001.50 | 77.50 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,810.00 | 865.00 | 2,945.00 | 77.30 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,714.70 | 3,768.20 | 12,946.50 | 77.46 |
| Approved Total (Overridden) (S\$) | | 3,000.00 | | |
| (S\$) | 16,714.70 | 3,000.00 | 13,714.70 | 82.05 |
| + GST 7.00/7.00% (S\$) | 1,170.03 | 210.00 | 960.03 | 82.05 |
| Nett Amount (S\$) | 17,884.73 | 3,210.00 | 14,674.73 | 82.05 |
| + Car Rental (5.0 x S\$100.00/day) (S\$) | | 500.00 | | |
| + Doc/Search Fee (S\$) | | 29.00 | | |
| Nett Liability (S\$) | | 3,739.00 | | |
| Global Sum Settlement (S\$) | | 3,700.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 18/06/2021 | Yee Auto Pte Ltd (HQ) |
| Date Inspected: | 18/06/2021 Inspected At: | 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY Singapore 575722 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-------------|------------|--------------|
| 1 | 1 | | *REAR NUMBER PLATE | Serviceable | 60.00 F | *- FL |
| 2 | 1 | | *REVERSE SENSOR CORNER-LH | Serviceable | 395.20 F | *- FL |
| 3 | 1 | | *REVERSE SENSOR CORNER-RH | Serviceable | 395.20 F | *- FL |
| 4 | 1 | | *REVERSE SENSOR CENTRE-LH | Shorted | 395.20 F | *261.50 FL |
| 5 | 1 | | *REVERSE SENSOR CENTRE-RH | Shorted | 395.20 F | *261.50 FL |
| 6 | 1 | | *REAR BOOT LID | Repair | 2,206.10 F | *- FL |
| 7 | 1 | | *REAR BOOT LID WEATHERSTRIP | Serviceable | 235.90 F | *- FL |
| 8 | 1 | | *REAR BOOT LID LOCK | Repair | 455.90 F | *- FL |
| 9 | 1 | | *REAR BOOT LID TITANIUM EMBLEM | Necessary | 125.60 F | *125.60 FL |
| 10 | 1 | | *REAR BOOT LID FOCUS EMBLEM | Necessary | 105.10 F | *105.10 FL |
| 11 | 1 | | *REAR BUMPER | Bent | 1,810.20 F | *1,310.00 FL |
| 12 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 740.10 F | *650.10 FL |
| 13 | 1 | | *REAR BUMPER REFLECTOR -LH | Serviceable | 128.50 F | *- FL |
| 14 | 1 | | *REAR BUMPER REFLECTOR -RH | Serviceable | 128.50 F | *- FL |
| 15 | 1 | | *REAR BUMPER BRACKET -LH | Repair | 132.20 F | *- FL |
| 16 | 1 | | *REAR BUMPER BRACKET -RH | Repair | 132.20 F | *- FL |
| 17 | 1 | | *REAR END PANEL | Repair | 295.00 F | *- FL |
| 18 | 1 | | *REAR END PANEL TOP GARNISH | Serviceable | 253.00 F | *- FL |
| 19 | 1 | | *REAR EXHAUST MUFFLER | Repair | 2,840.40 F | *- FL |
| 20 | 1 | | *REAR BOOT LID NUMBER PLATE GARNISH | Dented | 665.50 F | *581.00 FL |
| 21 | 1 | | *REAR BUMPER TOWING COVER | Serviceable | 85.50 F | *- FL |
| 22 | 1 | | *REAR BUMPER INNER IMPACT GARNISH | Cracked | 198.20 F | *198.20 FL |
| 23 | 1 | | *REAR TAILLAMP LOWER GARNISH -LH | Serviceable | 295.00 F | *- FL |
| 24 | 1 | | *REAR TAILLAMP LOWER GARNISH -RH | Serviceable | 295.00 F | *- FL |
| 25 | 1 | | *REVERSE SENSOR HOLDER CENTRE LH | Dented | 68.00 F | *68.00 FL |
| 26 | 1 | | *REVERSE SENSOR HOLDER CENTRE RH | Cracked | 68.00 F | *68.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (\$\$) | 12,904.70 | 3,629.00 |
| - List Item Discount on L Items 0.00/20.00% (\$\$) | 0.00 | 725.80 |
| Total Parts (\$\$) | 12,904.70 | 2,903.20 |

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY | New | 1,500.00 | 450.00 |
| 2 | TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION | New | 1,500.00 | 400.00 |
| 3 | TO APPLY RUST -PROOFING ON REPAIRED ,REPLACED PANEL | New | 120.00 | 0.00 |
| 4 | TO REMOVE /RENEW EXHAUST MUFFLER | New | 250.00 | 0.00 |
| 5 | TO CHECK WIRING FUNCTIONS | New | 80.00 | 15.00 |
| 6 | TO REMOVE/TRANSFER TAILGATE COMPONENTS | New | 80.00 | 0.00 |
| 7 | COMPUTER DIAGNOSTIC RESET | New | 280.00 | 0.00 |
| | | | Gross Labour Cost (\$) | 3,810.00 |
| | | | | 865.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >