



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6950L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR LH (WCP)	BUCKLED	650.00	650.00
1	FRONT DOOR PROTECTOR LH (WCP)	CRACKED	75.00	75.00
1	FRONT DOOR RUBBER LH (WCP)	NECESSARY	90.00	90.00
1	FRONT DOOR LOWER RUBBER LH (WCP)	NECESSARY	40.00	40.00
5	FRONT DOOR BLACK TAPE LH @\$40.00 (WCP)	NECESSARY	200.00	120.00
1	FRONT DOOR LOCK (WCP)	BENT	250.00	250.00
1	FRONT DOOR CATCH LH (WCP)	SERVICEABLE	35.00	-
1	REAR DOOR LH (WCP)	BUCKLED	650.00	650.00
1	REAR DOOR PROTECTOR LH (WCP)	CRACKED	80.00	80.00
1	REAR DOOR RUBBER LH (WCP)	NECESSARY	90.00	90.00
1	REAR DOOR LOWER RUBBER LH (WCP)	NECESSARY	46.00	46.00
5	REAR DOOR BLACK TAPE LH @\$40.00 (WCP)	NECESSARY	200.00	200.00
1	REAR DOOR LOCK (WCP)	BENT	260.00	260.00
1	REAR DOOR CATCH (WCP)	SERVICEABLE	35.00	-
1	REAR DOOR OUTER MOULDING LH (WCP)	CRACKED	75.00	75.00
2	REAR DOOR HINGE LH @\$48.00 (WCP)	BENT	96.00	96.00
1	REAR FENDER 1/4 GLASS C/W MOULDING LH (WCP)	CUT	390.00	390.00
1	ROCKER GARNISH LH (WCP)	TORN	390.00	390.00
10	ROCKER GARNISH CLIPS @\$5.00 (WCP)	NECESSARY	50.00	50.00
1	ROCKER PANEL LH (WCP)	TO REPAIR SEE LABOUR	300.00	-
2	ROCKER PANEL TOP GARNISH LH @\$75.00 (WCP)	SERVICEABLE	150.00	-
1	CENTRE PILLAR LH (WCP)	BENT	300.00	300.00
1	CENTRE PILLAR INNER MEMBER LH (WCP)	TO REPAIR SEE LABOUR	250.00	-
1	FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	COST PLUS 15%		705.30	577.80
			5,407.30	4,429.80



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER 1/4 GLASS SEALANT (SN) COST PLUS 15%	NECESSARY	40.00 6.00 46.00	40.00 - 40.00
	<b><u>LABOUR</u></b>			
	TO CUT & WELD CENTRE PILLAR LH, CENTRE INNER MEMBER LH, ROCKER PANEL LH, TO REPAIR LH FLOOR PANEL, REAR FENDER LH. TO REMOVE & REFIT DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF ROCKER PANEL LH, CENTRE PILLAR INNER MEMBER LH, FLOOR PANEL AND REAR FENDER LH.		1,400.00	900.00
	TO SPRAY AFFECTED AREAS.		1,200.00	800.00
	TO REMOVE & REFIX DOOR MECHANISM, TRANSFER DOOR POWER WINDOW, CHECK & TEST POWER WINDOW AND CENTRE LOCKING SYSTEM.		160.00	80.00
	TO REMOVE & REFIX SAFETY BELT, REAR CUSHION CARPET AND OTHER ATTACHMENT PARTS.		120.00	60.00
	TO PROGRAMMING ADAS SYSTEM.		200.00	100.00
	TO REMOVE & REFIX ROOF LINING, FRONT CUSHION & SAFETY BELT.		150.00	100.00
			3,230.00	2,040.00
<b>GRAND TOTAL</b>			<b>8,683.30</b>	<b>6,509.80</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>6,509.80</b>
<b>LESS EXCESS</b>			<b>-4,500.00</b>
<b>NETT LIABILITY</b>			<b>2,009.80</b>

Report Ref No. CS/LPC21006824/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.