

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AUTO & GENERAL	. INSURANCE (S) PL	Ref:	CS3/AGI21006825/T1vf3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924		Date:	02/08/2021	
			Code:	AGI	
1.					
	Insured Veh.	SMD 3157L	Veh. Inspected	FBM 5438X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010467/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	18/06/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA JUPITER MX	c.c	134	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	MH350C002CK482675	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	D/II F T	80/90 R17	ASPIRA	5 mm	
	R/H Front Tyre	00/30 1(17			
	L/H Front Tyre	00/30 1(17		mm	
	ļ <u> </u>	80/90 R17	ASPIRA	mm 5 mm	
	L/H Front Tyre				
4.	L/H Front Tyre R/H Rear Tyre	80/90 R17		5 mm	
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	80/90 R17	ASPIRA on of Damages	5 mm	
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	80/90 R17 Descripti STAINED DAMAGES AT THE O/S	ASPIRA on of Damages	5 mm	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	80/90 R17 Descripti STAINED DAMAGES AT THE O/S	ASPIRA on of Damages N/S BODY AND FRONT	5 mm	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSPORTION.	80/90 R17 Descripti STAINED DAMAGES AT THE O/S Genera	ASPIRA on of Damages N/S BODY AND FRONT Il Information	5 mm mm	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSPORTION. Accident Date	Descripti STAINED DAMAGES AT THE O/S Genera	ASPIRA on of Damages N/S BODY AND FRONT Inspect Date / Time	5 mm mm 18/06/2021 (06:00 PM)	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSPORTION. Accident Date	Descripti STAINED DAMAGES AT THE O/S Genera 05/06/2021 EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19	ASPIRA on of Damages N/S BODY AND FRONT Inspect Date / Time	5 mm mm 18/06/2021 (06:00 PM)	
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSPORTION. Accident Date Survey held at A) THE INSPECTION THE REPAIR ESTHE REPAIRER WC) ENCLOSED PLI	Descripti STAINED DAMAGES AT THE O/S Genera 05/06/2021 EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19	ASPIRA on of Damages N/S BODY AND FRONT Inspect Date / Time SYNERGY @KB SINGAP emarks THOUT PREJUDICE" BAS OAT THE TIME OF INSPETIMATE. PHOTOGRAPHS.	5 mm mm 18/06/2021 (06:00 PM) ORE 417800 IS. CTION.	
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUSPORTION. Accident Date Survey held at A) THE INSPECTION THE REPAIR ESTHE REPAIRER WC) ENCLOSED PLI	Descripti TAINED DAMAGES AT THE O/S Genera 05/06/2021 EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 R ON WAS CONDUCTED ON A "WI STIMATE WAS NOT PRESENTED AS TOLD TO PREPARE THE ESEASE FIND DAMAGED VEHICLE D REPAIR COST OF THE DAMA	ASPIRA on of Damages N/S BODY AND FRONT Inspect Date / Time SYNERGY @KB SINGAP emarks THOUT PREJUDICE" BAS OAT THE TIME OF INSPETIMATE. PHOTOGRAPHS.	5 mm mm 18/06/2021 (06:00 PM) ORE 417800 IS. CTION.	

Report Ref No. CS3/AGI21006825/T1vf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser