

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3719A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	DEFORMED	459.34	459.34
1	REAR BUMPER BEAM	CRACKED	394.80	394.80
1	REAR BUMPER BEAM BRACKET LH	NOT NECESSARY	138.10	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER MOULDING CENTRE	DEFORMED	451.25	451.25
1	REAR FOG LAMP	NOT NECESSARY	201.50	-
1	ANTENNA ASSY-SMARTKEY	NOT NECESSARY	40.50	-
1	REAR BUMPER TOW COVER	MISSING	98.80	98.80
	LESS 20% DISCOUNT		-361.26	-285.24
			1,445.03	1,140.95
	NETT ITEMS			
1	REAR BUMPER MAT (N)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-	-23.00
			230.00	207.00
	SPECIAL NETT ITEMS			
1	ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINT.		500.00	500.00
	CHECK WIRING.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,030.00	910.00
	GRAND TOTAL		2,755.03	2,307.95





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,850.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21006832/T1vcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser