

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006842/APA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070179107
Claimant Vehicle No :	SJT7819K	Insured Vehicle No :	SLJ6090E
Date of Loss:	21/06/2021	Nature of Claim:	TP
		Claim No:	0134827149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT7819K	Engine No:	EJ20D722346
Make & Model:	SUBARU FORESTER, 2.0 X (A)	Chassis No:	JF1SH5KS59G020964
Reg. Date:	29/10/2009 (Man. Year: 2009)	Odometer:	183428 km
Colour:	White		
Engine Capacity:	1994 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,543.54	6,047.62	1,495.92	19.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	2,350.00	500.00	17.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,393.54	8,397.62	1,995.92	19.20
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	10,393.54	6,700.00	3,693.54	35.54
+ GST 7.00/7.00% (S\$)	727.55	469.00	258.55	35.54
Nett Amount (S\$)	11,121.09	7,169.00	3,952.09	35.54
+ Loss of Use (10.0 x S\$85.00/day) (S\$)		850.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		8,175.45		
Global Sum Settlement (S\$)		8,150.00		

INSPECTION

Date of Assignment:	21/06/2021	
Date Inspected:	21/06/2021	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	713.04 FL	*713.04 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FL
4	1		*REAR BUMPER ENFORCEMENT	Bent	475.40 FL	*360.00 FL
5	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	225.40 FL	*112.70 FL
6	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	126.40 FL	*126.40 FL
7	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
8	1		*REAR END PANEL	Dented	423.04 FL	*423.04 FL
9	1		*REAR END PANEL INNER TRIM	Deformed	136.12 FL	*136.12 FL
10	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	16.00 FS	*16.00 FS
11	2		*REAR O/S & N/S TAIL LAMP RETAINER	Not Necessary	110.40 FL	*- FL
12	1		*REAR O/S & N/S TAIL LAMP (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR BOOT COVER	Dented	1,386.64 FL	*1,192.00 FL
14	1		*REAR BOOT COVER WEATHERSTRIP	Cut	245.44 FL	*245.44 FL
15	1		*REAR BOOT COVER FORESTER EMBLEM	Necessary	79.16 FL	*79.16 FL
16	1		*REAR BOOT COVER SUBARU EMBLEM	Necessary	73.56 FL	*73.56 FL
17	1		*REAR BOOT COVER STI EMBLEM	Necessary	79.60 FL	*79.60 FL
18	1		*REAR BOOT COVER INNER TRIM	Cracked	333.00 FL	*333.00 FL
19	11		*REAR BOOT COVER INNER TRIM CLIPS	Necessary	33.00 FS	*33.00 FS
20	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	372.36 FL	*200.00 FL
21	1		*REAR BOOT COVER LOCK (LOWER)	Not Necessary	79.10 FL	*- FL
22	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
23	1		*REAR WINDSCREEN MOULDING	Necessary	220.00 FS	*85.00 FS
24	1		*FRONT BUMPER	Deformed	713.04 FL	*713.04 FL
25	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*FRONT BUMPER ENFORCEMENT	Dented	445.96 FL	*445.96 FL
27	1		*FRONT BUMPER O/S & N/S RETAINER	O/S Cracked	121.60 FL	*60.60 FL
28	1		*FRONT SUPPORT PANEL (NPA)	Repair	0.00 FL	*- FL
29	1		*FRONT GRILLE	Cracked	751.40 FL	*585.00 FL
30	1		*FRONT GRILLE EMBLEM	Necessary	87.12 FL	*87.12 FL
31	6		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
32	1		*FRONT O/S HEAD LAMP	Cracked	1,440.40 FL	*920.00 FL
33	1		*FRONT REG.NO.PLATE	Dented	45.00 FS	*30.00 FS
34	1		*FRONT REG.NO.PLATE BRACKET	Deformed	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,227.18	7,424.78
- List Item Discount on L Items 20.00/20.00% (\$)	1,683.64	1,377.16
Total Parts (\$)	7,543.54	6,047.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,400.00	1,100.00
2	TO SPRAY PAINTING	New	1,000.00	900.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	30.00	30.00
4	TO REMOVE AND REPLACE REAR TAIL-GATE FITTINGS	New	80.00	80.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	140.00	120.00
6	TO CHECK WIRING	New	100.00	60.00
7	TO RE-SEAL ANTI-RUST	New	100.00	60.00
Gross Labour Cost (\$\$)			2,850.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >