

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006843/ATCN2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant: YAN JIE Policy No: 2100490068
Date of Loss: 14/06/2021 Nature of Claim: OD Claim No: 1028002184SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH9764K**
Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR019949
Reg. Date: 24/11/2016 (Man. Year: 2015) Chassis No: WAUZZZ4M0HD008373
Colour: Silver Odometer: 15319 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$225,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55R19 Rear Tyre Size: 255/55R19
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,467.00	759.20	9,707.80	92.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,502.00	4,102.00	5,400.00	56.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,969.00	4,861.20	15,107.80	75.66
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	18,969.00	3,861.20	15,107.80	79.64
+ GST 7.00/7.00% (S\$)	1,327.83	270.28	1,057.55	79.64
Nett Amount (S\$)	20,296.83	4,131.48	16,165.35	79.64

INSPECTION

Date of Assignment: 21/06/2021
Date Inspected: 17/06/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LOWER	Repair	2,070.00 FS	*- FS
2	1		*REAR DOOR-LH	Repair	5,311.00 FS	*- FS
3	1		*REAR DOOR OUTER SEAL-LH	Not Necessary	250.00 FS	*- FS
4	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
5	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
6	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
7	1		*REAR DOOR CATCH-LH	Not Necessary	105.00 FS	*- FS
8	1		*SEAL FOR SILL PANEL-LH	Not Necessary	253.00 FS	*- FS
9	1		*REAR DOOR COVER-LH	Not Necessary	600.00 FS	*- FS
10	2		*REAR WHEEL ARC TRIM-LH/RH	N/s Cut/O/s Necessary	754.00 FS	*602.40 FS
11	1		*REAR DOOR ARC TRIM-LH	Cut	196.00 FS	*156.80 FS
12	1		*REAR WHEEL HOUSING LINER LH	Not Necessary	320.00 FS	*- FS
13	1		*REAR WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **10,467.00** **759.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	450.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR.TO REPAIR LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,000.00	600.00
4	TO RESPRAY REAR UPPER BUMPER,REAR LOWER BUMPER,LHS REAR DOOR,LHS REAR DOOR COVER,LHS REAR FENDER.BOTH REAR WHEEL ARCH TRIMS AND LHS REAR DOOR WHEEL ARCH TRIM	New	5,500.00	2,950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	4,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >