

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006844/NRA3Q2
Date: 01/03/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210007951
Claimant Vehicle No :	SHC3578U	Insured Vehicle No :	SMX6606H
Date of Loss:	18/06/2021	Nature of Claim:	TP
		Claim No:	4909388305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3578U		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU298663
Reg. Date:	24/07/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164835
Colour:	Blue	Odometer:	222859 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,291.96	976.12	315.84	24.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,071.96	1,606.12	465.84	22.48
+ GST 7.00/7.00% (S\$)	145.04	112.43	32.61	22.48
Nett Amount (S\$)	2,217.00	1,718.55	498.45	22.48
+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
+ Car Rental (3.5 x S\$125.19/day) (S\$)		438.17		
		(S\$) 2,331.72		
Liabe Amount (50.00%) (S\$)		1,165.86		
+ Doc/Search Fee (S\$)		2.00		
		1,167.86		

INSPECTION

Date of Assignment:	21/06/2021		
Date Inspected:	21/06/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MLDG	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER BEAM	Serviceable	394.80 FL	*- FL
5	1		*REVERSE SENSOR	Deformed	180.00 FS	*180.00 FS
6	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,557.45	1,162.65
- List Item Discount on L Items 20.00/20.00% (\$)	265.49	186.53
Total Parts (\$)	1,291.96	976.12

LKK Auto Consultants Pte Ltd/SHC3578U/01/03/2022 15:53

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	630.00

LKK Auto Consultants Pte Ltd/SHC3578U/01/03/2022 15:53

< END OF ESTIMATES >