

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SMRT AUTOMOTI	VE SERVICES PTE LTD		Ref:	CS3/SMR21006848/Vuf3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	28/06/2021	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHF 253K	Veh. Inspected	k	SMJ 5685J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/06/21/2033	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		21/06/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	MR053ZEE106157794	Colour		BLACK	
	Odometer	172801 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA		5 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA		5 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA		5 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	16/06/2021	Inspect Date /	Time	21/06/2021 (12:30 PM)	
	Survey held at	GARAGE 13 PTE LTD	•			
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMR21006848/Vuf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser