

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.
Insurer's Mandate Remarks
If there is no evidence from TP to support their claim please deny the claim

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III21006849/UGS3Q2
Date: 13/09/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No	SMW8264C	Insured Vehicle No :	GBJ8816J
Date of Loss:	11/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002508

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW8264C	Engine No:	G4FMLU192279
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Chassis No:	KMHLN41ETMU094304
Reg. Date:	14/12/2020 (Man. Year: 2020)	Odometer:	11743 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,517.90	2,839.04	5,678.86	66.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,290.00	1,210.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,017.90	4,129.04	6,888.86	62.52
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	11,017.90	3,300.00	7,717.90	70.05
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	21/06/2021	Inspected At:	Choo Motor Spray Painter (HQ)
Date Inspected:	21/06/2021		

9/13/21, 4:45 PM

Merimen e-Claims

Estimated Period of Repair: 4.0 days

1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2021)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW8264C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,253.80 F	*- FL
2	1		*FRONT BUMPER	Distorted	699.70 F	*499.70 FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Bent	66.50 F	*62.20 FL
4	1		*FRONT BUMPER BEAM	Not Necessary	481.20 F	*- FL
5	1		*FRONT BUMPER SPONGE	Torn	140.80 F	*133.80 FL
6	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Grazed	65.00 F	*65.00 FL
7	1		*FRONT BUMPER TOP	Repair	241.20 F	*- FL
8	1		*FRONT BUMPER LOGO	Necessary	38.00 F	*38.00 FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
10	1		*FRONT GRILLE	Not Necessary	299.60 F	*- FL
11	1		*HEADLAMP HID O/S	Cracked	1,956.40 F	*1,756.40 FL
12	1		*FRONT FENDER O/S	Repair	1,227.70 F	*- FL
13	1		*FRONT FENDER INNER SHIELD O/S	Torn	212.80 F	*188.50 FL
14	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	45.00 F	*45.00 FL
15	1		*FRONT SUPPORT PANEL ASSY	Cracked / Twisted	745.20 F	*715.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,517.90	3,548.80
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	709.76
Total Parts (S\$)	8,517.90	2,839.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO RESET & REPROGRAMME SYSTEM	New	180.00	50.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	900.00	600.00
6	TO PUTTY & SPRAY PAINTING	New	1,200.00	520.00
Gross Labour Cost (S\$)			2,500.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >