

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006852/AGA3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070127190
Claimant Vehicle No :	SJT2642K	Insured Vehicle No :	GBB2099T
Date of Loss:	16/06/2021	Nature of Claim:	TP
		Claim No:	2125960226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT2642K		
Make & Model:	KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A)	Engine No:	G4FC9H295675
Reg. Date:	30/09/2009 (Man. Year: 2009)	Chassis No:	KNAFU411MA5128170
Colour:	Blue	Odometer:	162583 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,489.60	2,324.09	1,165.51	33.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	830.00	420.00	33.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,739.60	3,154.09	1,585.51	33.45
Approved Total (Overridden) (S\$)		2,500.00		

Nett Amount (S\$)	4,739.60	2,500.00	2,239.60	47.25
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,867.45		

INSPECTION

Date of Assignment: 17/06/2021

Date Inspected: 17/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ysk Auto Workshop (HQ)
No.1 Kaki Bukit Avenue 6, #01-49 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Dented	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*FRONT NUMBER PLATE GARNISH	Deformed	40.30 F	*40.30 FL
4	1		*FRONT BUMPER	Deformed	585.40 F	*585.40 FL
5	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
6	2		*FRONT BUMPER SIDE HOLDER	Necessary	51.00 F	*51.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Cracked	72.50 F	*72.50 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	243.60 F	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	92.40 F	*- FL
10	1		*FRONT GRILLE	Cracked	267.50 F	*267.50 FL
11	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*FRONT GRILLE LOGO	Necessary	48.00 F	*48.00 FL
13	1		*HEADLAMP	N/S Cracked	1,044.00 F	*522.00 FL
14	1		*BONNET	Dented	873.40 F	*873.40 FL
15	1		*BONNET LOCK	Not Necessary	61.50 F	*- FL
					Sub Total (\$\$)	3,489.60
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	3,489.60
						2,570.10
						246.01
						2,324.09

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	400.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$\$)			1,250.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >