

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006853/KPS3Q2
Date: 31/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119488
Claimant Vehicle No :	SMJ8526R	Insured Vehicle No :	SMU5421X
Date of Loss:	17/06/2021	Nature of Claim:	TP
		Claim No:	5944217130SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ8526R		
Make & Model:	TOYOTA NOAH, 1.8 (A)	Engine No:	2ZR2C29868
Reg. Date:	22/03/2019 (Man. Year: 2018)	Chassis No:	ZWR800362263
Colour:	Metallic Black	Odometer:	155432 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Windforce 5 mm	Rear Left Side:	Firenza 4 mm
Front Right Side:	Windforce 5 mm	Rear Right Side:	Firenza 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	785.90	635.90	150.00	19.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	640.00	300.00	31.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,725.90	1,275.90	450.00	26.07
+ GST 7.00/7.00% (S\$)	120.81	89.31	31.50	26.07

Nett Amount (S\$)	1,846.71	1,365.21	481.50	26.07
		<hr/>		
+ Loss of Use (2.0 x S\$99.00/day) (S\$)		198.00		
+ Doc/Search Fee (S\$)		2.00		
		<hr/>		
Nett Liability (S\$)		1,565.21		
		<hr/>		

INSPECTION

Date of Assignment: 21/06/2021

Date Inspected: 21/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
 Singapore 575643

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	581.20 FL	*581.20 FL
2	1		*REVERSE SENSOR	Dented / Shorted	350.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					931.20	781.20
- List Item Discount on L Items 25.00/25.00% (\$)					145.30	145.30
Total Parts (\$)					785.90	635.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSTALL REVERSE SENSOR	New	40.00	40.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	400.00	200.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	500.00	400.00
Gross Labour Cost (\$\$)			940.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >