



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JUN 6427

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FORK ASSY	SERVICEABLE	1,800.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	480.00	-
1	FRONT FENDER	CUT	135.00	105.00
1	FRONT RIM	TO REPAIR SEE LABOUR	580.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	70.00	-
1	MIRROR - R/H	SCRATCHED	180.00	95.00
1	FRONT SIGNALS - R/H	NOT NECESSARY	150.00	-
1	BRAKE LEVER	SCRATCHED	120.00	68.00
1	HANDLE-BAR	BENT	280.00	150.00
1	HANDLE-BAR END - R/H	SCRATCHED	95.00	35.00
1	FRONT SIDE FAIRING - R/H	CUT	220.00	220.00
1	FRONT FAIRING INNER SIDE COVER - R/H	SERVICEABLE	185.00	-
1	TANK SIDE COVER - R/H	CUT	285.00	285.00
1	FRONT SIDE LOWER COVER	SERVICEABLE	185.00	-
1	FRONT FOOTREST - R/H	DAMAGED	105.00	70.00
1	FRONT FOOTREST BRACKET - R/H	NOT NECESSARY	165.00	-
1	BRAKE PEDAL	CUT	135.00	135.00
1	REAR FOOTREST - R/H	CUT	105.00	70.00
1	REAR FOOTREST BRACKET - R/H	NOT NECESSARY	155.00	-
1	REAR SIDE COVER	SERVICEABLE	165.00	-
1	EXHAUST ASSY	DAMAGED	950.00	780.00
1	EXHAUST PROTECTOR	DAMAGED	180.00	148.00
1	RADIATOR COVER	DAMAGED	165.00	80.00
1	ENGINE COVER	TO REPAIR SEE LABOUR	680.00	-
	LESS 10% DISCOUNT		-757.00	-224.10
			6,813.00	2,016.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	FRT NECESSARY	38.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	68.00	-

Report Ref No. CS/TP21006861/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OIL SEALS (SN)	NOT NECESSARY	100.00	-
1	STEERING CONE (SN)	NOT NECESSARY	125.00	-
1	ENGINE OIL (SN)	NOT NECESSARY	120.00	-
1	ENGINE COVER GASKET (SN)	NOT NECESSARY	95.00	-
1	REAR BOX (SN)	GRAZED	480.00	300.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
1	FRONT TYRE (SN) (LOCAL PURCHASE) (\$180.00) (80%)	DAMAGED	245.00	144.00
1	REAR TYRE (SN) (LOCAL PURCHASE) (\$180.00) (80%)	DAMAGED	280.00	144.00
			1,731.00	598.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	450.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT RIM AND ENGINE COVER.		480.00	300.00
			1,010.00	300.00
GRAND TOTAL			9,554.00	2,914.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/TP21006861/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.