

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006862/KGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900012775
Claimant Vehicle No :	SMR6423A	Insured Vehicle No :	SDU7338Y
Date of Loss:	20/06/2021	Nature of Claim:	TP
		Claim No:	0545349941SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR6423A	Engine No:	FA20CB16035
Make & Model:	SUBARU FORESTER, 2.0 XT (A)	Chassis No:	JF1SJGK85JG099602
Reg. Date:	25/10/2017 (Man. Year: 2017)	Odometer:	48243 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,107.20	12,236.24	870.96	6.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	4,060.00	620.00	13.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,787.20	16,296.24	1,490.96	8.38
Approved Total (Overridden) (\$\$)		13,000.00		
(\$\$)	17,787.20	13,000.00	4,787.20	26.91
+ GST 7.00/7.00% (\$\$)	1,245.10	910.00	335.10	26.91
Nett Amount (\$\$)	19,032.30	13,910.00	5,122.30	26.91
+ Car Rental (13.0 x \$S\$120.00/day + 7.00% GST) (\$\$)		1,669.20		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		15,581.20		

INSPECTION

Date of Assignment:	21/06/2021	
Date Inspected:	22/06/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	14.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	600.30 FL	*600.30 FL
2	1		*REAR BUMPER LH REFLECTOR	Cracked	28.30 FL	*28.30 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Cracked	18.30 FL	*18.30 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	320.30 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
6	1		*REAR BUMPER TOP PROTECTOR	Dented	410.00 FL	*410.00 FL
7	1		*LH TAILLAMP (SPORT)	Broken	450.00 FS	*450.00 FS
8	1		*REAR LH FENDER	Buckled	960.10 FL	*960.10 FL
9	1		*REAR LH FENDER INNER SHIELD	Cracked	65.40 FL	*65.40 FL
10	8		*REAR LH FENDER INNER SHIELD CLIPS	Necessary	30.40 FL	*30.40 FL
11	1		*REAR LH FENDER AIR SCROP GRILLE	Distorted	60.30 FL	*60.30 FL
12	1		*REAR LH FENDER GLASS MOULDING	Serviceable	380.60 FL	*- FL
13	1		*REAR LH FENDER INNER GARNISH	Dented	208.50 FL	*208.50 FL
14	1		*REAR LH FENDER INNER FRONT RUBBER	Cut	64.30 FL	*64.30 FL
15	4		*REAR LH FENDER INNER FRONT RUBBER CLIPS	Necessary	15.20 FL	*15.20 FL
16	1		*REAR LH DOOR	Bent	801.70 FL	*801.70 FL
17	1		*REAR LH DOOR FRAME STICKER	Necessary	51.30 FL	*51.30 FL
18	1		*REAR LH DOOR INNER RUBBER	Serviceable	160.30 FL	*- FL
19	1		*REAR LH DOOR LOWER PRTOECTOR	Missing	192.80 FL	*192.80 FL
20	1		*LH SIDE SKIRT	Cracked	54.00 FL	*54.00 FL
21	1		*LH SIDE SKIRT LH END GARNISH MUD FLAP	Distorted	25.00 FL	*25.00 FL
22	8		*LH SJDE SKIRT CLIPS	Necessary	30.40 FL	*30.40 FL
23	1		*REAR TAILGATE	Bent	1,072.80 FL	*1,072.80 FL
24	1		*TAILGATE EMBLEM (SUBARU AWD)	Necessary	72.30 FL	*72.30 FL
25	1		*TAILGATE EMBLEM (FORESTER XT)	Necessary	72.30 FL	*72.30 FL
26	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	65.20 FL	*65.20 FL
27	1		*REAR EXHAUST PIPE LH	Bent	668.00 FL	*668.00 FL
28	1		*CENTRE EXHAUST PIPE	Bent	880.00 FL	*880.00 FL
29	1		*REAR EXHAUST PIPE TOP HEAT COVER	Bent	85.00 FL	*85.00 FL
30	1		*REAR PANEL	Bent	320.80 FL	*320.80 FL
31	1		*LH TAILLAMP PANEL	Bent	90.50 FL	*90.50 FL
32	1		*REAR LH SHOCK ABSORBER	Bent	720.00 FL	*720.00 FL
33	1		*REAR LH DRIVE SHAFT	Bent	780.00 FL	*780.00 FL
34	1		*REAR LH KNUCKLE ARM	Broken	270.00 FL	*270.00 FL
35	1		*REAR LH KNUCKLE ARM BEARING	Necessary	202.60 FL	*202.60 FL
36	1		*REAR LH CONTROL ARM (FOR ALIGNMENT)	Bent	228.00 FL	*228.00 FL
37	1		*REAR LH LOWER ARM	Bent	156.00 FL	*156.00 FL
38	1		*REAR LH TRAILING ARM	Bent	200.10 FL	*200.10 FL
39	1		*REAR CROSS MEMBER	Bent	760.20 FL	*760.20 FL
40	1		*REAR CROSS MEMBER LH BRACKET	Distorted	210.00 FL	*210.00 FL
41	1		*REAR LH UPPER ARM	Bent	480.20 FL	*480.20 FL
42	1		*REAR LH ABS WIRE SENSOR	Dented / Cut	280.00 FL	*280.00 FL
43	1		*REAR LH HAND BRAKE CABLE	Serviceable	65.00 FL	*- FL
44	1		*REAR LH FENDER GLASS GUM	Necessary	30.00 FS	*30.00 FS
45	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
46	1		*REAR LH TYRE (80%)	Punctured	350.00 FS	*280.00 FS
47	1		*UNIT REAR AXLE OIL (3 LTRS)	Necessary	60.00 FS	*60.00 FS
48	1		*SET SPORT RIMS	Bent / Cracked	2,200.00 FS	*2,200.00 FS
49	1		*REAR CROSS MEMBER LH BRACKET	Bent	127.00 FL	*127.00 FL
50	1		*LTR AXLE OIL (50%)	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,571.50	14,515.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,464.30	2,279.06
Total Parts (\$\$)	13,107.20	12,236.24

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (4 WHEEL TOWING)	New	100.00	100.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE & REFIX LH FENDER GLASS	New	100.00	60.00
4	REMOVE & REFIX SEAT ,CARPET ,GARNISH TOP ROOF LINING ETC	New	120.00	120.00
5	REMOVE & REFIX REAR LH UNDER CARRIAGE ,DRIVE SHAFT ,REAR AXLE ASSY ,ETC	New	280.00	240.00
6	REMOVE & REFIX EXHAUST ASSY & CHECK SYSTEM	New	100.00	80.00
7	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR LH DOOR & ATTACHMENT ,TAILGATE ASSY ,CUT ,WELD & RENEW REAR LH FENDER ,LH TAILLAMP PANEL ,REAR PANEL ,KNOCK & REPAIR REAR LH FENDER INNER PANEL ,REAR LH CHASSIS ,LH ROCKER PANEL & REALIGN THE SAME	New	2,000.00	1,700.00
8	REMOVE & REFIX REAR LH DOOR GLASS & CHECK CENTRAL LOCKING & POWER MIRROR	New	60.00	60.00
9	PUTTY & RESPRAY ON REAR LH DOOR ,LH ROCKER PANEL ,REAR LH FENDER ,REAR LH WHEEL HOUSING & CHASSIS ,TAILGATE ,REAR BUMPER ,REAR PANEL & ALL AFFECTED AREAS	New	1,600.00	1,400.00
10	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	80.00	60.00
11	RUSTPROOFING	New	120.00	120.00
Gross Labour Cost (\$\$)			4,680.00	4,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >