

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCN 6336H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	88.20	88.20
1	REAR WINDSCREEN (CONSISTENT)	NOT NECESSARY	1,650.00	-
1	TAILGATE (CONSISTENT)	DENTED / BENT	1,100.90	997.30
1	TAILGATE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	315.20	-
1	TAILGATE 'H' LOGO (CONSISTENT)	NOT NECESSARY	32.50	-
1	TAILGATE 'VEZEL' EMBLEM (CONSISTENT)	NECESSARY	56.50	56.50
1	TAILGATE 'HYBRID' EMBLEM (CONSISTENT)	NECESSARY	95.00	95.00
2	TAILGATE REFLECTORS @\$364.60(CONSISTENT)	NOT NECESSARY	729.20	-
1	TAILGATE INNER LOCK (CONSISTENT)	NOT NECESSARY	181.90	-
1	TAILGATE LOCK STRIKER (CONSISTENT)	NOT NECESSARY	48.60	-
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	368.20	-
1	SET TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
1	TAILGATE INNER HANDLE HOLDER (CONSISTENT)	NOT NECESSARY	32.00	-
2	TAILGATE DAMPERS @\$192.50(CONSISTENT)	NOT NECESSARY	385.00	-
1	TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	199.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED /DENTED	863.50	588.20
2	REAR BUMPER SIDES @\$395.10(CONSISTENT)	O/S DEFORMED	790.20	245.50
2	REAR BUMPER REFLECTORS @\$165.00(CONSISTENT)	NOT NECESSARY	330.00	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER UNDER COVER (CONSISTENT)	NOT NECESSARY	312.00	-
1	SET REAR BUMPER LOWER UNDER COVER CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
2	REAR BUMPER SIDE RETAINERS @\$45.00(CONSISTENT)	NOT NECESSARY	90.00	-
1	REAR END PANEL (CONSISTENT)	DENTED / BENT	517.00	517.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	188.00	188.00
2	TAILLAMPS @\$485.00(CONSISTENT)	O/S CRACKED	970.00	482.00
2	TAILLAMP HOUSING PANELS @\$350.00(CONSISTENT)	TO REPAIR SEE LABOUR	700.00	-
2	REAR FENDERS @\$991.00(CONSISTENT)	NOT NECESSARY	1,982.00	-
2	REAR FENDER INNER TRIMS @\$450.00(CONSISTENT)	NOT NECESSARY	900.00	-

Report Ref No. CC4/ASM21006868/Ups3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR EXHAUST (CONSISTENT)	NOT NECESSARY	785.20	-
1	REAR EXHAUST HEATSHIELD (CONSISTENT)	NOT NECESSARY	188.90	-
2	REAR FENDER OUTER PROTECTORS @\$299.00 (CONSISTENT)	O/S TORN	598.00	199.10
	LESS 50% DISCOUNT		-	-1,753.40
			14,647.00	1,753.40
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE W/HOLDER (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER TOP PROTECTOR (SN) (CONSISTENT)	DISTORTED	680.00	450.00
1	REAR END PANEL SEALANT (SN)(CONSISTENT)	NECESSARY	50.00	50.00
			1,110.00	540.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM .		100.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX FUEL TANK .	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING .		150.00	60.00
	TO MOUNT VEHICLE CAR O-LINER .	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS .		1,800.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,080.00
			4,780.00	2,220.00
	GRAND TOTAL		20,537.00	4,513.40



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		4,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21006868/Ups3q2

CHUA KANG SENG

Licensed Appraiser