

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA INSURANCE PTE LTD Ref: CC4/ASM2100686  8 SHENTON WAY #24-01 Date: 02/08/2021  AXA TOWERSINGAPORE 068811  ATTN:RICHARD ANG Code: ASM  1. Policy Particulars: - THIRD PARTY CLAIM  Insured Veh. SHD 9624A Veh. Inspected SCN 6336H  Policy No. VFX/P2413997 Coverage (\$) 0.00  Claim No. S1M03C45 Excess (\$) 0.00  Assign From Assign Date 21/06/2021	8/Ups3a2	
AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG  Code: ASM  1.		
Policy Particulars :- THIRD PARTY CLAIM           Insured Veh.         SHD 9624A         Veh. Inspected         SCN 6336H           Policy No.         VFX/P2413997         Coverage (\$)         0.00           Claim No.         S1M03C45         Excess (\$)         0.00		
Insured Veh.   SHD 9624A   Veh. Inspected   SCN 6336H		
Policy No.         VFX/P2413997         Coverage (\$)         0.00           Claim No.         S1M03C45         Excess (\$)         0.00	1. Policy Particulars :- THIRD PARTY CLAIM	
Claim No.         S1M03C45         Excess (\$)         0.00		
Assign From Assign Date 21/06/2021		
2. Vehicle Particulars & Condition		
Make & Model HONDA VEZEL HYBRID (A) c.c 1496		
Engine No. HIDDEN Year of Reg. 2017		
Chassis No. RU31254278 Colour GREY		
Odometer 242394 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre         215/60 R16         TOURADOR         6 mm		
L/H Front Tyre 215/60 R16 TOURADOR 6 mm		
R/H Rear Tyre 215/60 R16 TOURADOR 6 mm		
L/H Rear Tyre 215/60 R16 TOURADOR 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 19/06/2021 Inspection Date 21/06/2021		
Survey held at FASTECH AUTO PTE LTD		
1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days		