



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |   |   |            |
|--|--|---|---|------------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |  |   | Ref: CS/AGI21006870/Aqf3n2<br>Date: 30/07/2021<br><br>Code: AGI |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |   |   |            |
|  | Insured Veh.   | SFU 6885S   | Veh. Inspected  | SMD 9485A  |
|  | Policy No.   |   | Coverage (\$)   | 0.00       |
|  | Claim No.  | C10010572/HA  | Excess (\$)   | 0.00       |
|  | Assign From  | IVY RATILLA   | Assign Date   | 21/06/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |   |   |            |
|  | Make & Model   | HYUNDAI ELANTRA   | c.c   | 1591       |
|  | Engine No.   | HIDDEN  | Year of Reg.  | 2018       |
|  | Chassis No.  | KMHD841CMJU686473   | Colour  | BEIGE      |
|  | Odometer   | 49394 KM  | Steering  | IN ORDER   |
|  | Brakes   | IN ORDER  | Modification  | SPORTS RIM |
|  | General  | GOOD  |   |            |
| <b>3. Conditions of Tyres</b>  |  |   |   |            |
|  |  | Size  | Make  | Balance    |
|  | R/H Front Tyre   | 195/65 R15  | YOKOHAMA  | 6 mm       |
|  | L/H Front Tyre   | 195/65 R15  | YOKOHAMA  | 6 mm       |
|  | R/H Rear Tyre  | 195/65 R15  | YOKOHAMA  | 6 mm       |
|  | L/H Rear Tyre  | 195/65 R15  | YOKOHAMA  | 6 mm       |
| <b>4. Description of Damages</b>   |  |   |   |            |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |   |            |
| <b>5. General Information</b>  |  |   |   |            |
|  | Accident Date  | 18/06/2021  | Inspection Date   | 22/06/2021 |
|  | Survey held at   | TWINCAR AUTOMOTIVE PTE LTD<br>2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |   |            |
| <b>5a. Remarks</b>   |  |   |   |            |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |            |
| <b>5b. Estimate Days of Repair</b>   |  |   |   |            |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 4 Working Days  |            |