

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006872/R1GA3Q2
Date: 27/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLK9452U	Insured Vehicle No :	SMX3467L
Date of Loss:	13/05/2021	Nature of Claim:	TP
		Claim No:	7586492524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9452U	Engine No:	CAXF82923
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A)	Chassis No:	WVWZZZ16ZGM007918
Reg. Date:	07/02/2017 (Man. Year: 2015)	Odometer:	76146 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,105.35	1,156.13	2,949.22	71.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,000.00	1,200.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,305.35	2,156.13	4,149.22	65.80
Approved Total (Overridden) (S\$)		1,700.00		

(S\$)	6,305.35	1,700.00	4,605.35	73.04
+ GST 7.00/7.00% (S\$)	441.37	119.00	322.37	73.04
Nett Amount (S\$)	6,746.72	1,819.00	4,927.72	73.04
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/06/2021

Date Inspected: 23/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Forza Autohaus Pte Ltd (HQ)
 No.39 Woodlands Close, #01-34/35, Mega@Woodlands
 Singapore 737856

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RIM LH	Scratched	405.00 FS	*350.00 FS
2	1		*FRONT DOOR LOCK LH	Not Necessary	1,312.40 FL	*- FL
3	1		*FRONT FENDER LH	Repair	672.50 FL	*- FL
4	1		*FRONT BUMPER RETAINER LH	Not Necessary	12.40 FL	*- FL
5	1		*FRONT BUMPER	Repair	1,218.50 FL	*- FL
6	1		*FRONT DOOR SIDE MIRROR ASSY LH	Cracked	895.70 FL	*895.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,516.50	1,245.70
- List Item Discount on L Items 10.00/10.00% (\$)	411.15	89.57
Total Parts (\$)	4,105.35	1,156.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	300.00
2	TO PROVIDE LABOUR ,WORKMANSHIP TO CHAGE THE ABOVE DAMAGED BODYPARTS REPAIR ,REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
Gross Labour Cost (\$\$)			2,200.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >