



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5407Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / CRACKED	638.00	638.00
8	REAR BUMPER CLIPS	NECESSARY	31.20	31.20
1	REAR BUMPER N/S BRACKET	SERVICEABLE	13.90	-
1	REAR BUMPER N/S RETAINER	BENT	14.60	14.60
1	REAR TAIL-LAMP PANEL	SERVICEABLE	300.50	-
1	REAR TAIL-LAMP PANEL INNER TRIM	SERVICEABLE	60.80	-
4	REAR TAIL-LAMP PANEL INNER TRIM CLIPS	SERVICEABLE	18.00	-
1	REAR N/S TAIL-LAMP	CRACKED	226.20	226.20
1	REAR N/S TAIL-LAMP SEALANT	SERVICEABLE	14.60	-
1	REAR BOOT COVER	DENTED / BENT	610.70	610.70
1	REAR BOOT COVER WEATHERSTRIP	SERVICEABLE	97.60	-
1	REAR BOOT COVER EMBLEM	NECESSARY	26.70	26.70
1	REAR BOOT COVER INSULATOR	SERVICEABLE	133.70	-
1	REAR BOOT COVER N/S REFLECTOR	CRACKED	145.90	145.90
1	REAR BOOT COVER N/S REFLECTOR SEALANT	SERVICEABLE	14.00	-
2	REAR BOOT COVER O/S & N/S STOPPER	SERVICEABLE	14.00	-
2	REAR BOOT COVER O/S & N/S HINGES	SERVICEABLE	97.20	-
1	REAR BOOT COVER LOCK (LOWER)	SERVICEABLE	15.00	-
1	REAR BOOT COVER LOCK (UPPER)	BENT	194.50	194.50
2	REAR BOOT COVER LOCK WASHER (UPPER)	SERVICEABLE	7.60	-
1	REAR BOOT COVER LOCK SNAP (UPPER)	SERVICEABLE	4.00	-
1	REAR BOOT COVER LOCK SILENCER (UPPER)	SERVICEABLE	3.80	-
1	REAR O/S FENDER INNER TRIM	SERVICEABLE	145.90	-
8	REAR O/S FENDER INNER TRIM CLIPS	SERVICEABLE	36.00	-
	LESS 20% DISCOUNT		-572.88	-377.56
			2,291.52	1,510.24
SPECIAL NETT ITEMS				
1	REAR REVERSE SENSOR (SN)	CRACKED	380.00	200.00
			380.00	200.00

Report Ref No. CS3/AIG20012035/Eqf3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE REAR PORTION DAMAGED PARTS, STRAIGHTEN REAR BOOT FLOOR PANEL, REAR SPARE WHEEL HOUSING PANEL, REAR N/S CHASSIS FRAME AND REWELD REAR TAIL-LAMP PANEL.		900.00	500.00
	TO PUTTY AND SPRAY PAINTING.		1,000.00	500.00
	TO REMOVE AND REPLACE REAR TAIL-LAMP PANEL INNER TRIM AND REAR N/S FENDER INNER TRIM.	NOT NECESSARY	180.00	-
	TO CHECK WIRING.		60.00	30.00
	TO RE-SEAL ANTI RUST.		180.00	30.00
	TOWING CHARGE.		80.00	60.00
			2,400.00	1,120.00
	GRAND TOTAL		5,071.52	2,830.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS3/AIG20012035/Eqf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.