



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 2897G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRONT HEADLAMP LH/RH @\$874.10	O/S CRACKED	1,748.20	643.00
2	FRONT HEADLAMP LOWER BRACKET LH/RH @\$27.50	NOT NECESSARY	55.00	-
2	FRONT BUMPER RETAINER LH/RH @\$23.40	NECESSARY	46.80	46.80
1	FRONT BUMPER REINFORCEMENT	DENTED	253.20	253.20
2	FRONT FENDER INNER SHIELD LH/RH @\$77.40	NOT NECESSARY	154.80	-
	LESS 20% DISCOUNT		-451.60	-188.60
			1,806.40	754.40
	<u>SPECIAL NETT ITEMS</u>			
2	FRONT HEADLAMP CLIPS SET LH/RH @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER (MUGEN)(SN)	CRACKED	1,400.00	800.00
1	SET FRONT BUMPER FOG LAMP (SN)	CRACKED	550.00	250.00
1	SET FRONT BUMPER NUMBER PLATE WITH CASING (SN)	DENTED	65.00	65.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
			2,175.00	1,145.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.		1,000.00	300.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		600.00	200.00
	TO APPLY ANTI-RUST & TUFF KOTE.	NOT NECESSARY	105.00	-
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
			1,785.00	530.00
GRAND TOTAL			5,766.40	2,429.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/AGI21006885/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.