



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 9612G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	994.60	994.60
10	REAR BUMPER CLIPS @\$5.80	NECESSARY	58.00	58.00
1	REAR BUMPER RETAINER LH	SERVICEABLE	52.80	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	52.80	-
1	REAR BOOT LID	TO REPAIR SEE LABOUR	861.20	-
1	REAR BOOT EMBLEM	NECESSARY	68.20	68.20
1	REAR BOOT MAZDA 2 STICKER	NECESSARY	57.90	57.90
6	REAR BOOT INSULATOR CLIPS @\$5.80	NOT NECESSARY	34.80	-
	LESS 20% DISCOUNT		-436.06	-235.74
			1,744.24	942.96
	<u>SPECIAL NETT ITEMS</u>			
1	REAR PARKING SENSOR (SN)	SERVICEABLE	280.00	-
			280.00	-
	<u>LABOUR</u>			
	TO KNOCK RR END PANEL,WELD,REMOVE & FIX ON ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		750.00	500.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		800.00	600.00
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	80.00	-
			1,660.00	1,100.00
	GRAND TOTAL		3,684.24	2,042.96
	RECOMMENDED COST OF REPAIRS			2,042.96

Report Ref No. CS/SMR21006887/R1uf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.