24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

### VEHICLE INSPECTION REPORT

To: Chew Chiew Huan Nerissa

Date

: 29 April 2021

C/o: GForce Autotech Private Limited

Our ref

: GFA/04/2101/TP

10 Kaki Bukit Road

#01-34 Singapore 417868

Accident Date

: 12 April 2021

Type of Survey: Third Party

Inspection Date

: 13 April 2021

Repairer Name

: GForce Autotech Private Limited

10 Kaki Bukit Road

#01-34 Singapore 417868

# PARTICULARS OF VEHICLE

Registration No

: SMY 9699 P

Year / Capacity:

2014 / 1997 cc

Make / Model

: BMW 420i

Colour

Pearl Black

Chassis No

: WBA3N12050F994916

Mileage

157826

Engine No

: A3190696N20B20B

### **CONDITION OF TYRES**

		Make	Size	Thread Balance	Rim
Front Nearside	:	Michelin	245/35 R19	5 mm	Sport
Front Offside	:	Michelin	245/35 R19	5 mm	Sport
Rear Nearside	:	Michelin	245/35 R19	5 mm	Sport
Rear Offside	:	Michelin	245/35 R19	5 mm	Sport

# GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front n/s portion.

(Details refer to the photographs attached)

Enclosed number of photographs:

48

copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$10,100.00 on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.

Page 1



Vehicle Registration No.: SMY 9699 P

Our Ref No.:

GFA/04/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
	SPARE PARTS - LIST ITEMS			
1	Front bonnet	Damage	\$ 2,383.60	\$ 2,383.60
1	Front n/s headlamp	Damage	\$ 4,041.05	\$ 4,041.05
1	Front n/s headlamp lower bracket	Damage	\$ . 113.00	\$ 113.00
1	Front n/s headlamp washer nozzle pen	Damage	\$ 125.00	\$ 125.00
1	Front n/s headlamp washer nozzle cover	Damage	\$ 75.00	\$ 75.00
1	Front bumper	Damage	\$ 1,653.55	\$ 1,653.55
1	Front bumper fog lamp	Intact	\$ 471.40	
1	Front bumper reinforcement	Damage	\$ 726.00	\$ 726.00
1	Front bumper n/s PDC sensor	Damage	\$ 303.80	\$ 303.80
1	Front bumper n/s side retainer	Necessary	\$ 136.20	\$ 136.20
1	Front n/s fender	Damage	\$ 933.00	\$ 933.00
1	Front n/s fender inner shield	Intact	\$ 132.50	
		•	\$ 11,094.10	\$ 10,490.20
		Less 5%	\$ 554.71	\$ 524.51
	Total Cost - List Items		\$ 10,539.40	\$ 9,965.69
	<u>SPECIAL NETT ITEMS</u>			
1	Front bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00
-	Total Cost - Special Nett items		\$ 60.00	\$ 60.00

Total cost of parts

\$ 10,599.40	\$ 10,025.69



Vehicle Registration No.: SMY 9699 P

Our Ref No.:

GFA/04/2101/TP

S/No	Description		Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	10,599.40	\$	10,025.69	
	<u>LABOUR</u>					
1	To check wiring, lighting and resetting headlamps focusing.	\$	80.00	\$	50.00	
2	To apply undercoating on repaired and replaced panel.	\$	100.00	\$	60.00	
3	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,400.00	\$	1,000.00	(
4	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,800.00	\$	1,500.00	
	GRAND TOTAL	\$	13,979.40	\$	12,635.69	



Vehicle Registration No.: SMY 9699 P Our Ref No.: GFA/04/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 10,100.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser





























































