

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte L
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 9699P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BONNET | DAMAGED | 2,383.60 | 1,574.80 |
| 1 | FRONT N/S HEADLAMP | DAMAGED | 4,041.05 | 2,620.00 |
| 1 | FRONT N/S HEADLAMP LOWER BRACKET | DAMAGED | 113.00 | 113.00 |
| 1 | FRONT N/S HEADLAMP WASHER NOZZLE PEN | DAMAGED | 125.00 | 125.00 |
| 1 | FRONT N/S HEADLAMP WASHER NOZZLE COVER | DAMAGED | 75.00 | 75.00 |
| 1 | FRONT BUMPER | DAMAGED | 1,653.55 | 1,042.20 |
| 1 | FRONT BUMPER FOG LAMP | NOT NECESSARY | 471.40 | - |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | 726.00 | - |
| 1 | FRONT BUMPER N/S PDC SENSOR | DAMAGED | 303.80 | 303.80 |
| 1 | FRONT BUMPER N/S SIDE RETAINER | NECESSARY | 136.20 | 136.20 |
| 1 | FRONT N/S FENDER | DAMAGED | 933.00 | 865.00 |
| 1 | FRONT N/S FENDER INNER SHIELD | NOT NECESSARY | 132.50 | - |
| | LESS 5% DISCOUNT | | -554.71 | -342.75 |
| | | | 10,539.39 | 6,512.25 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET FRONT BUMPER CLIP (SN) | NECESSARY | 60.00 | 30.00 |
| | | | 60.00 | 30.00 |
| | <u>LABOUR</u> | | | |
| | TO CHECK WIRING,LIGHTING AND RESETTING HEADLAMPS FOCUSING. | | 80.00 | 30.00 |
| | TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL. | | 100.00 | 30.00 |
| | TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD.RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. | | 1,400.00 | 700.00 |
| | TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT. | | 1,800.00 | 1,000.00 |
| | | | 3,380.00 | 1,760.00 |
| | GRAND TOTAL | | 13,979.39 | 8,302.25 |

Report Ref No. CS3/LPC21004664/T1vf3e2-1



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 6,650.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS3/LPC21004664/T1vf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.