

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21006894/KPA3Q2
Date: 06/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993738
Claimant Vehicle No :	SHD5855B	Insured Vehicle No :	GBC7644G
Date of Loss:	19/06/2021	Nature of Claim:	TP
		Claim No:	5466426385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5855B		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B60430
Reg. Date:	01/11/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU603075136
Colour:	Metallic Pearl White/Red	Odometer:	254252 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,910.52	1,126.95	6,783.57	85.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	600.00	2,990.00	83.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,500.52	1,726.95	9,773.57	84.98
+ GST 7.00/7.00% (S\$)	805.04	120.89	684.15	84.98

Nett Amount (S\$)	12,305.56	1,847.84	10,457.72	84.98
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$96.30/day) (S\$)		192.60		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,147.89		
Global Sum Settlement (S\$)		2,140.00		

INSPECTION

Date of Assignment: 21/06/2021

Date Inspected: 21/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,REAR BUMPER	Mtg Cracked	442.60 FL	*442.60 FL
2	1		*GUARD ,REAR BUMPER ,CENTER	Dented	576.30 FL	*576.30 FL
3	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Mtg Cracked	123.70 FL	*123.70 FL
4	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
7	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
8	1		*LENS AND BODY ,REAR LAMP LH	Serviceable	502.00 FL	*- FL
9	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Serviceable	443.30 FL	*- FL
10	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
11	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
12	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
13	1		*GARNISH SUB -ASSY ,BACK DOOR ,OUTSIDE	Repair	925.60 FL	*- FL
14	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
15	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
16	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
17	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
18	1		*PARKING AID	Dented	700.00 FS	*220.00 FS
19	1		*FENDER CLIP	Not Necessary	130.00 FS	*- FS
20	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
21	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
22	1		*RIM	Serviceable	1,879.40 FS	*- FS
23	1		*HUB CAP	Serviceable	211.50 FS	*- FS
24	1		*SET CLIP ,ROCKER PANEL MOULDING	Serviceable	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,510.40	1,412.60
- List Item Discount on L Items 25.00/25.00% (\$)	1,599.88	285.65
Total Parts (\$)	7,910.52	1,126.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	400.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$)			3,590.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >