

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006895/ATCE2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant:	WONG TUCK HUEI	Policy No:	
Date of Loss:	18/06/2021	Nature of Claim:	OD Claim No: 8725295955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ1942G	Engine No:	CHZC31207
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V8KA096455
Reg. Date:	31/10/2019 (Man. Year: 2019)	Odometer:	37087 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,313.00	10,074.64	11,238.36	52.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,202.00	6,102.00	4,100.00	40.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,515.00	16,176.64	15,338.36	48.67
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	31,215.00	15,876.64	15,338.36	49.14
+ GST 7.00/7.00% (S\$)	2,185.05	1,111.36	1,073.69	49.14
Nett Amount (S\$)	33,400.05	16,988.00	16,412.05	49.14

INSPECTION

Date of Assignment:	22/06/2021	
Date Inspected:	21/06/2021	Inspected At: 24 BENOI SECTOR
Estimated Period of Repair:	8.0 days	Repairer: Premium Automobiles Pte Ltd

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION RH	Not Necessary	39.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	536.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Cracked	297.00 FS	*237.20 FS
7	1		*FRONT BUMPER COVER TRIM RH	Not Necessary	163.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER ADAPTOR RH	Not Necessary	38.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Not Necessary	188.00 FS	*- FS
12	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
13	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
14	1		*FRONT REINFORCEMENT BEAM	Dented	795.00 FS	*636.00 FS
15	1		*REINFORCEMENT BEAM FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
16	1		*REINFORCEMENT BEAM COVER	Cracked	122.00 FS	*97.20 FS
17	1		*SIGNAL HORN RH	Not Necessary	200.00 FS	*- FS
18	1		*FRONT FENDER RH	Buckled	851.00 FS	*680.40 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
20	1		*FRONT FENDER BRACKET RH	Buckled	28.00 FS	*21.84 FS
21	1		*FRONT FENDER BRACE RH	Bent	96.00 FS	*76.48 FS
22	1		*FRONT WHEEL HOUSING LINER RH	Not Necessary	169.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART RH	Not Necessary	89.00 FS	*- FS
24	1		*BONNET	Repair	3,134.00 FS	*- FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
26	2		*BONNET HINGE LH / RH	Not Necessary	124.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Not Necessary	90.00 FS	*- FS
28	2		*BONNET STRIKER LH / RH	Not Necessary	220.00 FS	*- FS
29	1		*BONNET EDGE PROTECTION	Not Necessary	28.00 FS	*- FS
30	2		*BONNET LOCK WITH MICRO SWITCH	Not Necessary	427.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE CENTER	Not Necessary	58.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE COVER CENTER	Not Necessary	10.00 FS	*- FS
33	1		*LED HEADLIGHT RH	Cracked	5,455.00 FS	*4,364.00 FS
34	1		*HEADLIGHT POWER MODULE RH	Not Necessary	758.00 FS	*- FS
35	1		*LED WITH HEAT SINK RH	Not Necessary	733.00 FS	*- FS
36	1		*HEADLIGHT CONTROL UNIT RH	Not Necessary	557.00 FS	*- FS
37	1		*HEADLIGHT BREATHER HOSE RH	Not Necessary	40.00 FS	*- FS
38	1		*LIFT CYLINDER RH	Not Necessary	142.00 FS	*- FS
39	1		*LIFT CYLINDER HOSE RH	Not Necessary	68.00 FS	*- FS
40	1		*LOCK CARRIER	Cracked	727.00 FS	*581.60 FS
41	1		*RADIATOR AIR GUIDE RH	Cracked	25.00 FS	*19.44 FS
42	1		*RADIATOR AIR GUIDE RH - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
43	6		*RADIATOR COOLANT	Necessary	266.00 FS	*214.56 FS
44	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
45	1		*SUNDRIES	Necessary	350.00 FS	*20.64 FS
46	1		*FRONT FENDER BRACKET - RH REAR	Bent	39.00 F	*30.72 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **21,313.00** **10,074.64**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER CONTROL	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCOND CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,250.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, HINGES AND BONNET	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,202.00	6,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >