



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |  |                 |  |  |
|---|--|-----------------|--|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSE SINGAPORE 199555  |  |                 | Ref: CS3/LPC21002446/R1vf3e2-1<br>Date: 02/07/2021<br>Code: LPC2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                 |  |  |
| Insured Veh.  | YN 3653B   | Veh. Inspected  | SJW 4018J  |  |
| Policy No.  |  | Coverage (\$)   | 0.00   |  |
| Claim No.   | 20/21/21/VC00/024210   | Excess (\$)     | 0.00   |  |
| Assign From   | KENNY LIM  | Assign Date     | 22/06/2021   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                 |  |  |
| Make & Model  | HONDA FIT 1.3G A   | c.c             | 1339   |  |
| Engine No.  | HIDDEN   | Year of Reg.    | 2010   |  |
| Chassis No.   | GE61144552   | Colour          | RED  |  |
| Odometer  | 117008 KM  | Steering        | IN ORDER   |  |
| Brakes  | IN ORDER   | Modification    | SPORTS RIM   |  |
| General   | FAIR   |                 |  |  |
| <b>3. Conditions of Tyres</b>   |  |                 |  |  |
|   | Size   | Make            | Balance  |  |
| R/H Front Tyre  | 185/65 R14   | DUNLOP          | 5 mm   |  |
| L/H Front Tyre  | 185/65 R14   | DUNLOP          | 5 mm   |  |
| R/H Rear Tyre   | 185/65 R14   | DUNLOP          | 5 mm   |  |
| L/H Rear Tyre   | 185/65 R14   | DUNLOP          | 5 mm   |  |
| <b>4. Description of Damages</b>  |  |                 |  |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.<br>DAMAGES SEE DETAILS.  |  |                 |  |  |
| <b>5. General Information</b>   |  |                 |  |  |
| Accident Date   | 04/02/2021   | Inspection Date | 22/02/2021   |  |
| Survey held at  | WILLY MOTOR COMPANY<br>27A JURONG PORT ROAD #01-32<br>SINGAPORE 619101 |                 |  |  |
| <b>5a. Remarks</b>  |  |                 |  |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |  |  |
| <b>5b. Estimate Days of Repair</b>  |  |                 |  |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:   |  |                 | 12 Working Days  |  |