PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers 227 Simei St 4 #06 – 42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To: NANI RAHAYU BTE MUHAMAD SANI C/O 27A Jurong Port #01-32 Singapore 619101

REFERENCE

Assigned By : As above

Accident Date : 04 February 2021 **Assignment Date** : 19 February 2021

: 19 February 2021 Inspection Date

Our Reference No. : PAS/WM/210310/TP

INSURANCE DETAILS

Insured

Policy No. / Claim No. : •

Sum Insured

Excess Clause Windscreen Coverage : -

Type of Claims : Third Party Claims

Third Party Insurer Third Party Policy No.: -

Inspection Report Date: 15 March 2021

Workshop Name:

WILLY MOTOR COMPANY

Inspection Address:

27A Jurong Port #01-32 Singapore 619101

PARTICULARS OF VEHICLE

Registration No. : SJW 4018 J

: HONDA FIT 1.3G A Make/Model

Yr of Manuf/Regn : 22 Mar 2010 Carrying Capacity : 4 Seater

Chassis No. : GE61144552 : L13A4156690 Engine No. : Metallic Red Colour

 Passenger (Private) Class

Mileage

: 117008

Km/h

Fitted Radio/Casette CD Disc Player : Fitted

: Fitted Air Conditioner

Clock : Fitted

: Fitted Seat Belt

Wing Mirror Other : Fitted

: Fitted Accessories

PRE-ACCIDENT CONDITION (Static Check Only) VEHICLE VALUE

Body Work

: Good

Paint Work : Good

Handbrake : Serviceable Footbrake : Serviceable

: Serviceable Steering

: None Any Apparent

Eng Modifications

Market Value : APPROXIMATELY \$26,000.00

Wreck Value (Parf): APPROXIMATELY \$13,372.00

TYRE SIZE & CONDITION

: 185/65R14 Front N/s Size

80 %

Front O/s Size

185/65R14

80 %

Make

: PIRELLI

Make

PIRELLI

Rear N/s size

: 185/65R14

Rear O/s Size

185/65R14

Make

PIRELLI

Make

PIRELLI

BO %

: 185/65R14

Spare Size

Spare Size : PIRELLI Make

80 %

80 %

Make Jack & Tools

Intact/Missing

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES


Insurance Loss Assessors/Adjusters CargoSurveyors & Licensed Appraisers

VEHICLE REGISTRATION NO.: SJW 4018 J

APPENDIX A

REAR





GENERAL DESCRIPTION OF DAMAGES

Parts damaged were: The front and rear ols door, ols centre door pillar and top rooftop panel, front ols door mirror, rear ols fender and wheel arch were dented

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 22/02/2021 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Willy Motor Company as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$8,550.00 after deducting the Policy Excess Clause of \$NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's				<u>Our</u>		
	Est	imate	Amou	nt	Re	vised	Amount
Spares Parts	:	9331	30			6311	84
Towing Charges	:	300	00	_		240	00_
PS Labour Charges	,	2400	00	_		1800	00
	· —	1520	00	-		1170	00
Others Misc Charges Paintwork	:	1600	00	_		1200	00
-	: \$	15151	30	_	S	10721	84

Under normal circumstances, the duration of repairs should not exceed <u>Twelve(12)</u> days including Pre-Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame and Public Holidays.

Attached photographs taken during inspection One Hundred & Twenty - Four (124) Photographs.

SPECIAL REMARKS

- The inspection was conducted on a 'without prejudice' basis
- On 23/02/2021, we examined the damaged parts.
- On 25/02/2021, we examined the extent of damages.
- 4. On 02/03/2021, we examined the repaired vehicle.

Yours Faithfully,

TFNG PHILIPFOO ACII CAE, AMIMI AIAME, AMSAE-A

Licaneed Annraicar/Adjuster

. ----

VEHICLE REGN NO :

SJW 4018 J

OUR REFERENCE :

PAS/WM/210310/TP

15-Mar-21

APPRAISEMENT SCHEDULE

		· 1	•	Repairer's	Recommendation /	
S/No	Oty	Parts / Labour Descriptions	Remarks / Condition	Estimate Amount	Revised Amoun	
[PARTS SUPPLY - LIST ITEMS		\$ cts	\$ cts	
1	1pc	Front O/s Door	Badly Dented	1046.40	1046.40	
2	1pc	Front O/s Door outer handle assy	Bent	79.20	79.20	
3	1pc	Front O/s door mirror assembly	Cracked	498.40	498.40	
4	1pc	Front O/s door sash tape set	Necessary	41.30	41.30	
5	1pc	Front O/s door lower sash	Necessary	26.70	2 6. 70	
6	1pc	Front O/s door run channel	Bent	52.20	52.20	
7	1pc	Front O/s door lock assembly	Bent	210.00	210.00	
8	1pc	Front O/s door weatherstrip	Torn	86.50	<i>86.50</i>	
9	1pc	Front O/s door striker	Bent	27.50	27.50	
10	1pc	Front O/s Door board	Warped/Cracked	388.40	388.40	
11	1pc	Front O/s Door black tape, rear	Necessary	44.20	44.20	
12	1pc	Front O/s door quarter glass mldg	Necessary	118.80	118.80	
13	1pc	Front O/s door quarter glass	Cracked	252.80	252.80	
14	1pc	Front O/s door glass	Broken	398.20	398.20	
15	1pc	Front O/s door upper hinge	Bent	48.60	48.60	
16	1pc	Front O/s door lower hinge	Bent	48.60	48.60	
17	1pc	Front O/s Door window regulator	Bent	383.90	383.90	
18	1pc	Front O/s door outer mldg	Dented	64.20	64.20	
19	1pc	Front O/s door checker	Bent	38.60	38.60	
20	1pc	Front O/s door inner lock	Bent/Jammed/Cracked	261.60	261.60	
21	1pc	Rear O/s door	Badly Dented	990.60	990.60	
22	1pc	Rear O/s Door black tape, front	Necessary	38.20	38.20	
23	1pc	Rear O/s Door black tape, rear	Necessary	38.20	38.20	
24	1pc	Rear O/s door sash tape set	Necessary	41.30	41.30	
25	1pc	Rear O/s Door window regulator	Bent	373.90	373.90	
26	1pc	Rear O/s door lower sash	Necessary	26.70	26.70	
27	1pc	Rear O/s door run channel	Bent	52.20	52.20	
28	·	Rear O/s door lock assembly	Bent	210.00	210.00	
29	1pc	Rear O/s door outer handle assy	Bent	78.40	78.40	
30	1pc	Rear O/s door upper hinge	Bent	48.60	48.60	
- 1	1pc	.,	Bent	48.60	48.60	
31	1pc	Rear O/s door lower hinge		86.50	86.50	
32	1pc	Rear O/s door weatherstrip	Torn	27.50	27.50	
33	1pc	Rear O/s door striker	Bent	t .		
34	1pc	Rear O/s door checker	Bent Saminochla	41.90	41.90	
35	1pc	Rear O/s Door board	Serviceable	388.40	20.00	
36	1pc	Rear O/s door checker	Bent Seet/Issues of	38.60	38.60	
37	1pc	Rear O/s door inner lock	Bent/Jammed	238.60	238.60	
38	1pc	Rear O/s fender quarter glass midg	Necessary	126.90	126.90	
39	1pc	Rear O/s wheel house	Badly Dented	456.60	Repair	
40	1pc	Rear O/s fender	Bodly dented	905.80	905.80	
41	1pc	O/s Taillamp	Broken	206.20	206.20	
42	3pcs	O/s Taillamp clip@\$5	Necessary	15.00	15.00	
43	1pc	O/s Taillamp pad	Necessary.	15.00	15.00	
44	1pc	O/s centre door pillar	Badly Dented	621.50	Repair	
			B/F SUB / GRAND TOTAL	<u>9231.30</u>	<u>7764.80</u>	

PRECISION APPRAISAL SERVICES

VEHICLE REGN NO :

SJW 4018 J

OUR REFERENCE :

PAS/WM/210310/TP

INSPECTION REPORT DATE: 15-Mar-21

CONTINUATION SHEET NO:


APPRAISEMENT SCHEDULE


1


S/No Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation Revised Amoun	
				\$ cts	\$ cts
			B/F	9231.30	7764.80
				•	<u>1552.96</u>
				9231.30	6211.84
		SPECIAL NETT ITEMS			
1	1Set	Front O/s fender quarter glass seq	lant Necessary	50.00	50.00
2	1Set	Rear O/s fender quarter glass seal	ant Necessary	50.00	50.00
		Total Spare Parts		9331.30	6311.84
		LABOUR & MISC. CHARGES			
		Towing - 2trips		300.00	240.00
1		Remove and refit front o/s door m	irror	50.00	30.00
2		Remove the necessary affected pa	rts, cut/weld		
		rear o/s fender, straighten front o	/s door pillar	2400.00	1800.00
		and centre door pillar, o/s top roo	ftop panel, rear		
		o/s wheel house and replace parts			
3		Remove and refit front o/s door po	arts	150.00	120.00
4		Remove and refit rear o/s door po	rts	150.00	120.00
5		Putty and Spraypaint on all affect	ed parts	1600.00	1200.00
6		Check electrical		100.00	80.00
7		Tuff Kote		150.00	120.00
8		Reset wheel alignment		100.00	80.00
9		Remove and refit rear bumper ser	sors	100.00	60.00
10		Rewire rear portion		50.00	30.00
11		Remove and refit front o/s fender	quarter glass	150.00	120.00
12		Remove and refit rear o/s fender	<u>-</u>	150.00	120.00
13	•	Vacuum broken glasses		20.00	20.00
[4		Remove and refit rear seats, roof	ning and trimmings	200.00	150.00
15		Remove and refit interior trim & g		150.00	120.00
		wheel rim to facilitate repair			1.
		Note: Recommended lump sum		·	
		repair at \$8,550.00nett.			

PRECISION APPRAISAL SERVICES

an










PRECISION APPRAISAL SERVICES







































































































































































































PRECISION APPRAISAL SERVICES















