

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21006898/EVCN2**Date:** 12/10/2021**REFERENCE**

Insured/Claimant: NI SHICHANG, KEVIN Policy No: 2070179107  
Date of Loss: 21/06/2021 Nature of Claim: OD Claim No: 0134827149SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLJ6090E**  
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC21588  
Reg. Date: 30/12/2020 (Man. Year: 2020) Chassis No: WAUZZZF36M1054631  
Colour: Black Odometer: 10368 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$156,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/65R17 Rear Tyre Size: 215/65R17  
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm  
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	37,742.00	19,570.48	18,171.52	48.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,522.00	6,922.00	8,600.00	55.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>53,264.00</b>	<b>26,492.48</b>	<b>26,771.52</b>	<b>50.26</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	52,864.00	26,092.48	26,771.52	50.64
<b>+ GST 7.00/7.00% (S\$)</b>	3,700.48	1,826.47	1,874.01	50.64
<b>Nett Amount (S\$)</b>	<b>56,564.48</b>	<b>27,918.95</b>	<b>28,645.53</b>	<b>50.64</b>

**INSPECTION**

Date of Assignment: 22/06/2021  
Date Inspected: 22/06/2021 Inspected At: 24 BENOI SECTOR  
SINGAPORE 629857  
REPAIRER: PREMIUM AUTOMOBILES PTE LTD  
Estimated Period of Repair: 9.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,815.00 FS	*2,251.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	118.00 FS	*- FS
4	1		*FRONT BUMPER CENTER TRIM (MANHATTAN GREY)	Not Necessary	356.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	217.00 FS	*- FS
6	2		*FRONT BUMPER SENSOR SUPPORT	Not Necessary	50.00 FS	*- FS
7	1		*FRONT BUMPER LOWER COVER-CENTER	Not Necessary	51.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	190.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Not Necessary	763.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER BRACKET	Not Necessary	21.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	306.00 FS	*- FS
12	2		*FRONT BUMPER AIR GUIDE TRIM-LH/RH	Not Necessary	328.00 FS	*- FS
13	2		*FRONT BUMPER SIDE SENSOR SUPPORT-LH/RH	Not Necessary	50.00 FS	*- FS
14	1		*FRONT RADIATOR GRILLE	Broken	1,928.00 FS	*1,542.40 FS
15	1		*FRONT RADIATOR GRILLE STRIKER PLATE	Broken	244.00 FS	*194.80 FS
16	1		*FRONT RADIATOR GRILLE LOGO COVER	Not Necessary	56.00 FS	*- FS
17	1		*FRONT BUMPER BRACKET	Not Necessary	41.00 FS	*- FS
18	1		*FRONT BUMPER SECURING PLATE	Not Necessary	33.00 FS	*- FS
19	1		*FRONT RADIATOR GRILLE COVER	Broken	244.00 FS	*194.80 FS
20	1		*FRONT CAMERA	Not Necessary	1,141.00 FS	*- FS
21	1		*FRONT BUMPER CARRIER	Not Necessary	916.00 FS	*- FS
22	1		*FRONT BUMPER CARRIER FOAM	Not Necessary	102.00 FS	*- FS
23	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	78.00 FS	*- FS
24	1		*FRONT BUMPER TOP COVER	Broken	123.00 FS	*98.00 FS
25	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
26	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
27	2		*FRONT BUMPER PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
28	4		NPA *FRONT BUMPER PARKING AID SENSOR SEAL	Not Necessary	16.00 FS	*- FS
29	1		*FRONT BUMPER WIRING SET	Torn	572.00 FS	*479.20 FS
30	2		*HORN-LH/RH	Not Necessary	267.00 FS	*- FS
31	2		*HORN BRACKET-LH/RH	Not Necessary	44.00 FS	*- FS
32	2		*FRONT FENDER-LH/RH	Not Necessary	2,572.00 FS	*- FS
33	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
34	2		*FRONT FENDER BRACE-LH/RH	Not Necessary	176.00 FS	*- FS
35	2		*FRONT FENDER BRACKET-LH/RH	Not Necessary	64.00 FS	*- FS
36	2		*FRONT WHEEL HOUSING LINER-LH/RH	Not Necessary	480.00 FS	*- FS
37	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
38	1		*FRONT BONNET	Dented	3,508.00 FS	*2,806.40 FS
39	2		*FRONT BONNET HINGE-LH/RH	Not Necessary	146.00 FS	*- FS
40	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
41	2		*FRONT BONNET STRIKER-LH/RH	Not Necessary	220.00 FS	*- FS
42	1		*FRONT BONNET SOUND ABSORBER	Not Necessary	219.00 FS	*- FS
43	1		*FRONT BONNET IMPACT PROTECTION	Necessary	28.00 FS	*21.84 FS
44	1		*FRONT BONNET LOCK	O/s Bent	427.00 FS	*170.80 FS
45	1		*FRONT BONNET RELEASE ELEMENT	Not Necessary	58.00 FS	*- FS
46	1		*FRONT BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
47	1		*FRONT BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
48	1		*FRONT BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
49	2		*FRONT HEADLIGHT MOUNTING-LH/RH	Broken	236.00 FS	*188.80 FS
50	2		*FRONT HEADLIGHT-LH/RH	Cut	11,178.00 FS	*8,942.40 FS
51	2		*FRONT HEADLIGHT LIFT CYLINDER-LH/RH	Not Necessary	420.00 FS	*- FS
52	2		*FRONT WHEEL ARCH TRIM-LH/RH	Necessary	1,072.00 FS	*857.60 FS
53	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
54	1		*FRONT LOCK CARRIER	Broken	1,272.00 FS	*1,017.60 FS
55	1		*A/C CONDENSER	Dented	551.00 FS	*440.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		<b>*TEMPERATURE SENSOR</b>	Not Necessary	7.00 FS	*- FS
57	1		<b>*ADDITIONAL RADIATOR</b>	Not Necessary	920.00 FS	*- FS
58	1		<b>*RADIATOR</b>	Not Necessary	1,035.00 FS	*- FS
59	1		<b>*COOLANT</b> (6 Pcs)	Necessary	266.00 FS	*214.56 FS
60	1		<b>*RADIATOR AIR GUIDE-LH/RH/UPPER/LOWER</b>	Broken	160.00 FS	*59.52 FS
61	1		<b>*FRONT TOP AIR GUIDE</b>	Not Necessary	56.00 FS	*- FS
62	1		<b>*INTAKE AIR DUCT COVER</b>	Not Necessary	29.00 FS	*- FS
63	1		<b>*INTAKE AIR GUIDE</b>	Not Necessary	20.00 FS	*- FS
64	1		<b>*INTAKE AIR GUIDE HOSE</b>	Not Necessary	34.00 FS	*- FS
65	1		<b>*FRONT NO PLATE</b>	Bent	60.00 FS	*60.00 FS
66	1		<b>*SUNDRIES</b>	Necessary	400.00 FS	*12.80 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 37,742.00 19,570.48**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR.RADIATOR,CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,BOTH FENDERS AND BOTH HEADLIGHT,RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,400.00	2,500.00
5	TO RESPRAY FRONT BUMPER,FRONT BUMPER SPOILER,BOTH FRONT FENDER.HINGES,BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	5,900.00	1,500.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REAPPLY PAINT COATING FOR AFFECTED AREA.(BY OWNER)	New	50.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,522.00</b>	<b>6,922.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >