

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21006900/EGS3Q2
Date: 05/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100463610
Claimant Vehicle No :	SMH7604R	Insured Vehicle No :	SKL2298B
Date of Loss:	19/06/2021	Nature of Claim:	TP
		Claim No:	1345286970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7604R	Engine No:	CZD189360
Make & Model:	SKODA OCTAVIA, 1.4 TSI (A)	Chassis No:	TMBBC7NE1K0071918
Reg. Date:	31/01/2019 (Man. Year: 2018)	Odometer:	20153 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,360.92	47.32	1,313.60	96.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,730.00	3,160.00	4,570.00	59.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,090.92	3,207.32	5,883.60	64.72
+ GST 7.00/7.00% (S\$)	636.36	224.51	411.85	64.72

Nett Amount (S\$)	9,727.28	3,431.83	6,295.45	64.72
		+ Loss of Use (5.0 x S\$50.00/day) (S\$)	250.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	3,683.83	

INSPECTION

Date of Assignment: 25/06/2021

Date Inspected: 25/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FOIL RHS REAR FENDER FOIL	Necessary	47.32 FS	*47.32 FS
2	1		*ALLOYWHEEL	Repair	1,310.00 FS	*- FS
3	1		*RUBBER VALVE	Not Necessary	3.60 FS	*- FS
					Total Parts (\$)	1,360.92
						47.32

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WHEEL ALIGNMENT	New	360.00	360.00
2	R&R RIM & BALANCE	New	50.00	0.00
3	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
4	DIAGNOSTIC AND PROGRAMMING	New	480.00	360.00
5	SPRAY PAINTING	New	3,200.00	1,600.00
6	LABOUR	New	3,360.00	840.00
Gross Labour Cost (S\$)			7,730.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >