

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM21006906/Vvce2		
	8 SHENTON WAY SINGAPORE 0688		Date:	07/07/2021		
	ATNN: KHONG LY		Code:	ASM		
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SCV 3366Z	Veh. Inspected		SLR 4818U	
	Policy No.	GA478936	Coverage (\$)		0.00	
	Claim No.	S1M03C69	Excess (\$)		0.00	
	Assign From	KHONG LYNN	Assign Date		22/06/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA3 SEDAN 1.5 AT	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0154203	Colour		WHITE	
	Odometer	44653 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	TRIANGLE		5 mm	
	L/H Front Tyre	205/60 R16	TRIANGLE		5 mm	
	R/H Rear Tyre	205/60 R16	TRIANGLE		5 mm	
	L/H Rear Tyre	205/60 R16	TRIANGLE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5. General Information						
	Accident Date	21/06/2021	Inspect Date /	Time	22/06/2021 (04:30 PM)	
	Survey held at	PRECISE AUTO SERVICE				
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM21006906/Vvce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser