

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21006907/R1RA3Q2
Date: 15/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070161006
Claimant Vehicle No :	SHD6128K	Insured Vehicle No :	GBK220A
Date of Loss:	20/06/2021	Nature of Claim:	TP
		Claim No:	4635853317SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6128K	Engine No:	2ZR6551643
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U805766681
Reg. Date:	06/11/2015 (Man. Year: 2015)	Odometer:	532911 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,178.16	2,291.40	12,886.76	84.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,868.00	1,170.00	2,698.00	69.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,046.16	3,461.40	15,584.76	81.83
Approved Total (Overridden) (S\$)		3,050.00		

Nett Amount (S\$)	19,046.16	3,050.00	15,996.16	83.99
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (7.0 x S\$107.00/day) (S\$)		749.00		
(S\$)		4,149.00		
Liabie Amount (90.00%) (S\$)		3,734.10		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,741.10		
Global Sum Settlement (S\$)		3,700.00		

INSPECTION

Date of Assignment: 21/06/2021

Date Inspected: 21/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: MOHD RASUL**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ADVERTISEMENT STICKER (SN)	Necessary	445.32 F	*296.88 F
2	1		*HOOD HINGE RH	Not Necessary	55.90 F	*- F
3	1		*HEAD LAMP LH	Serviceable	945.20 F	*- F
4	1		*DOOR FRT /LH	Repair	894.40 F	*- F
5	1		*FENDER LINER PAD ,FR WHEEL ,LH	Not Necessary	49.30 F	*- F
6	1		*FENDER APRON SUB FRT /LH	Serviceable	637.80 F	*- F
7	1		*WHEEL DISC FRONT	Repair	1,484.20 F	*- F
8	1		*TYRE	Serviceable	126.74 F	*- F
9	1		*MOULDING BODY LH	Not Necessary	673.60 F	*- F
10	1		*TIE ROD END LH	Not Necessary	159.30 F	*- F
11	1		*WHEEL HUB FRT	Serviceable	549.70 F	*- F
12	1		*FENDER LINER FRT/LH (DISC 25%)	Deformed	171.70 F	*128.78 F
13	1		*SEAL FRONT FENDER TO COWL SIDE LH	Serviceable	15.20 F	*- F
14	1		*PROTECTOR FRONT FENDER SIDE PANEL LH	Serviceable	114.50 F	*- F
15	1		*FENDER PROTECTOR FRT/LH UPPER	Serviceable	46.10 F	*- F
16	1		*NAME PLATE (HYBTRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
17	1		*FENDER FRT/LH (DISC 25%)	Buckled	723.40 F	*542.55 F
18	1		*COVER OUTER MIRROR LH	Not Necessary	107.40 F	*- F
19	1		*MIRROR LAMP LH	Not Necessary	65.30 F	*- F
20	1		*MIRROR ASSY LH	Not Necessary	1,224.90 F	*- F
21	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
22	1		*QUARTER GLASS FRT/LH	Not Necessary	234.90 F	*- F
23	1		*CHECK ASSY ,FR DOOR	Not Necessary	150.30 F	*- F
24	1		*HINGE UPPER LHF ,DOOR	Not Necessary	80.50 F	*- F
25	1		*HINGE LOWER LHF, DOOR	Not Necessary	90.10 F	*- F
26	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
27	1		*PILLAR ,FR BODY ,LH	Not Necessary	363.10 F	*- F
28	1		*HOOD HINGE LH	Not Necessary	55.90 F	*- F
29	1		*HOOD PANEL	Not Necessary	748.10 F	*- F
30	1		*UNDER COVER SIDE /LH	Not Necessary	46.10 F	*- F
31	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
32	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
33	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
34	1		*GRILLE RADIATOR LOWER NO.2	Not Necessary	94.60 F	*- F
35	1		*GRILLE RADIATOR	Not Necessary	310.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*COVER ,RADIATOR	Not Necessary	122.80 F	*- F
37	1		*LENS & BODY FR TURN LH	Not Necessary	511.80 F	*- F
38	1		*FOG LAMP LH	Not Necessary	280.10 F	*- F
39	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Not Necessary	311.10 F	*- F
40	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
41	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
42	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
43	1		*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F
44	1		*BUMPER SUPPORT F/RH	Not Necessary	76.40 F	*- F
45	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
46	1		*BUMPER FRT (DISC 25%)	Deformed	482.00 F	*361.50 F
47	1		*HEAD LAMP LH (DISC 10%)	Cracked	945.20 F	*850.68 F
					Total Parts (S\$)	15,178.16
						2,291.40

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	2,592.00	650.00
3	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
6	TO REPLACE SUNDPRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,868.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >