



No 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No.: 200723252D

Report Reference : **TP / 21009-01/AY / 2021**

Date of Report : **21 Jan 2021**

MK Vehicle Rental Pte Ltd
c/o 48 Toh Guan Road East
#04-124/125 Enterprise Hub
Singapore 608586

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 3 Jan 2021

Workshop Address : MK Vehicle Engineering Pte Ltd
48 Toh Guan Road East
#04-124/125 Enterprise Hub
Singapore 608586

As per your instruction dated **6 Jan 2021** with regard to the above matter. We have carried out a physical inspection on the said vehicle **YM 7386 B**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: YM 7386 B	Engine No	: 4M42A47288
Model	: Mitsubishi FE83	Mileage	: 254856
Year / Capacity	: 2007/2977	Colour	: White
Chassis No	: FE83BEA10300		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	: 7.00-16	Casumina	6.00 mm	Normal
REAR O/S	: 7.00-16	GT	6.00/6.00 mm	Normal
FRONT N/S	: 7.00-16	Casumina	6.00 mm	Normal
REAR N/S	: 7.00-16	GT	6.00/6.00 mm	Normal



No 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No.: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete.
5. Enclosed number of photograph : 156 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **YM 7386 B**
 Report No: **TP/ 21009-01/AY / 2021**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
2	Rear taillamps	O/S Damage	\$ 587.30	\$ 293.65
1	Rear o/s mudguard	Repair	\$ 169.20	\$
1	Front o/s headlamp	Damage	\$ 676.95	\$ 676.95
1	Front o/s side lamp	Damage	\$ 242.65	\$ 242.65
1	Front o/s signal lamp	Damage	\$ 332.40	\$ 332.40
1	Front panel	Damage	\$ 854.50	\$ 854.50
1	Front grille	Damage	\$ 453.63	\$ 453.63
1	Front grille logo	Necessary	\$ 85.00	\$ 85.00
1	Front bumper	Damage	\$ 961.95	\$ 961.95
2	Front bumper brackets	Damage	\$ 378.50	\$ 378.50
			<u>\$ 4742.08</u>	<u>\$ 4279.23</u>
<u>Special Nett Items</u>				
1	Rear bumper assy	Damage	\$ 650.00	\$ 650.00
1	Rear number plate	Damage	\$ 60.00	\$ 45.00
1	Rear o/s chassis (wooden)	Damage	\$ 600.00	\$ 600.00
1	Rear wooden tailboard assy	Damage	\$ 850.00	\$ 850.00
1	Rear tailboard lower member	Damage	\$ 420.00	\$ 420.00
1	Rear tailboard lower member (wood)	Damage	\$ 300.00	\$ 300.00
1	Rear step panel	Damage	\$ 180.00	\$ 180.00
1	Front panel sticker	Necessary	\$ 50.00	\$ 50.00
1	Front number plate	Damage	\$ 60.00	\$ 45.00
			<u>\$ 3170.00</u>	<u>\$ 3140.00</u>

Spare Parts Total \$ 7912.08 \$ 7419.23

Vehicle No: **YM 7386 B**
Report No: **TP/ 21009-01/AY / 2021**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7912.08	\$ 7419.23
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2000.00	\$ 1320.00
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2000.00	\$ 1540.00
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 60.00
6	Remove and refit rear platform for repair.	\$ 600.00	\$ 400.00
Total		<u>\$ 12712.08</u>	<u>\$ 10819.23</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 8700.00

SDLS: EIGHT THOUSAND SEVEN HUNDRED ONLY



Qualified Appraiser









































































































