

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006910/EQCN2**Date:** 21/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00016092102

Claimant Vehicle No : SKK1986K **Insured Vehicle No :** GBJ2687D

Date of Loss: 21/06/2021 Nature of Claim: TP Claim No: SNM21D203500/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK1986K**

Make & Model: CITROEN DS7 CROSSBACK, 1.6 PURETECH 180 EAT8 (A) Engine No: 10FKA72526574

Reg. Date: 17/09/2020 (Man. Year: 2019) Chassis No: VR1J45GFRKY027058

Colour: Red Odometer: 15398 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R19 Rear Tyre Size: 235/50 R19

Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm

Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,253.00	7,509.00	2,744.00	26.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,725.00	4,985.00	1,740.00	25.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,978.00	12,494.00	4,484.00	26.41
+ GST 7.00/7.00% (S\$)	1,188.46	874.58	313.88	26.41
Nett Amount (S\$)	18,166.46	13,368.58	4,797.88	26.41

INSPECTION

Date of Assignment: 22/06/2021

Date Inspected: 01/07/2021 Inspected At: Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Sep 2021)	
Parts:	N/A	CITROEN DS7 CROSSBACK 1.6 PURETECH 180 EAT8 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK1986K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,518.00 FS	*1,518.00 FS
2	1		*RECESS DOOR	Broken	74.00 FS	*74.00 FS
3	1		*BUMPER MOULDING LH	Dented	717.00 FS	*717.00 FS
4	1		*BUMPER MOULDING	Cut	255.00 FS	*255.00 FS
5	1		*FIX STIFFENER LH	Not Necessary	142.00 FS	*- FS
6	1		*BUMPER ABSORBER	Broken	533.00 FS	*533.00 FS
7	1		*BUMPER BRACKET	Not Necessary	167.00 FS	*- FS
8	1		*ABSORBER SET	Not Necessary	140.00 FS	*- FS
9	1		*LOW RR PAN FIX	Necessary	152.00 FS	*152.00 FS
10	1		*FIXING STUD	Necessary	32.00 FS	*32.00 FS
11	1		*REAR PANEL ASS	Not Necessary	561.00 FS	*- FS
12	1		*TAILGATE A PEINDRE	Dented	3,101.00 FS	*3,101.00 FS
13	1		*TAILGATE GLASS	Not Necessary	492.00 FS	*- FS
14	1		*TAILGATE FIX	Necessary	185.00 FS	*185.00 FS
15	1		*BADGE	Necessary	61.00 FS	*61.00 FS
16	1		*BADGE	Necessary	59.00 FS	*59.00 FS
17	1		*SENSOR	Cut	192.00 FS	*192.00 FS
18	1		*WING MOULDING LH	Crushed	249.00 FS	*249.00 FS
19	1		*TAIL-LIGHT LH	Broken	204.00 FS	*204.00 FS
20	1		*TAILGATE MOULDING	Not Necessary	149.00 FS	*- FS
21	1		*BADGE	Necessary	117.00 FS	*117.00 FS
22	1		*SENSOR	Not Necessary	192.00 FS	*- FS
23	1		*TAIL-LIGHT LH	Not Necessary	901.00 FS	*- FS
24	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
25	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					10,253.00	7,509.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, TAILGATE & AFFECTED AREA. REPAIR REAR END PANEL	New	3,040.00	1,520.00
2	REMOVE & INSTALL TAILGATE GLASS	New	300.00	300.00
3	REMOVE & INSTALL PARKING SENSOR	New	120.00	120.00
4	REMOVE & INSTALL TAILGATE TRIMS AND REAR COMPARTMENT TRIMS	New	300.00	280.00
5	SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR END PANEL	New	1,650.00	1,650.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	50.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	380.00	380.00
8	APPLY SEALANT FOR TAILGATE GLASS	New	80.00	80.00
9	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	200.00	0.00
10	REPAIR REAR END PANEL	New	380.00	380.00
11	RESPRAY REAR END PANEL	New	225.00	225.00
Gross Labour Cost (\$\$)			6,725.00	4,985.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >