

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21006916/AVF3E2

Date: 29/07/2021

REFERENCE

Insured/Claimant:	-	Policy No:	D20MPC0001554-01		
Date of Loss:	19/06/2021	Nature of Claim:	OD	Claim No:	MPC2021D0002602

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6498X		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B5561181
Reg. Date:	18/04/2019 (Man. Year: 2018)	Chassis No:	RU11311164
Colour:	Blue	Odometer:	57066 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,000.16	10,840.00	6,160.16	36.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,090.00	1,760.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,850.16	12,930.00	7,920.16	37.99
Approved Total (Overridden) (S\$)		10,300.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	20,250.16	9,700.00	10,550.16	52.10

INSPECTION

Date of Assignment: 22/06/2021

Date Inspected: 23/06/2021 Inspected At:

Estimated Period of Repair: 9.0 days

Jec Auto Service (HQ)
1 KAKI BUKIT AVENUE 6 #02-11, Autobay @ Kaki
Bukit
Singapore 417883

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK6498X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	821.40 FL	*821.40 FL
2	2		*FRONT BUMPER SIDE HOLDER	Necessary	53.00 FL	*53.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	321.00 FL	*321.00 FL
4	2		*FRONT BUMPER REINFORCEMENT TOP MOULDING	Deformed	70.00 FL	*70.00 FL
5	1		*FRONT BUMPER TOW COVER	Not Necessary	27.00 FL	*- FL
6	1		*FRONT BUMPER UNDERCOVER	Torn	319.40 FL	*319.40 FL
7	1		*FRONT BUMPER LOWER GRILLE	Deformed	162.90 FL	*162.90 FL
8	2		*FRONT BUMPER FOG LAMP	Not Necessary	655.40 FL	*- FL
9	2		*FRONT BUMPER FOG LAMP BRACKET	Not Necessary	96.00 FL	*- FL
10	2		*FRONT BUMPER FOG LAMP GARNISH	Deformed	170.00 FL	*170.00 FL
11	1		*FRONT BUMPER LOWER GARNISH	Deformed	386.20 FL	*386.20 FL
12	1		*FRONT BUMPER LOWER GARNISH RUBBER	Not Necessary	84.90 FL	*- FL
13	1		*FRONT GRILLE	Cracked	351.80 FL	*351.80 FL
14	1		*FRONT GRILLE INNER	Cracked	225.10 FL	*225.10 FL
15	1		*FRONT GRILLE CHROME MOULDING	Cracked	283.90 FL	*283.90 FL
16	1		*FRONT GRILLE LOGO	Necessary	35.90 FL	*35.90 FL
17	2		*HEADLAMP	Cracked	3,569.00 FL	*3,569.00 FL
18	2		*HEADLAMP LOWER BRACKET	Cracked	78.00 FL	*78.00 FL
19	1		*FRONT AMBIENCE TEMPERATURE SENSOR	Not Necessary	45.00 FL	*- FL
20	1		*FRONT AMBIENCE TEMPERATURE SENSOR BRACKET	Not Necessary	25.00 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Buckled	676.60 FL	*676.60 FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	190.30 FL	*- FL
23	1		*AIR CON CONDENSER	Dented	898.00 FL	*898.00 FL
24	2		*AIR CON CONDENSER MOUNTING	Necessary	50.00 FL	*50.00 FL
25	2		*AIR CON CONDENSER SIDE GUIDE	Not Necessary	72.00 FL	*- FL
26	1		*AIR CON FAN BLADE	Not Necessary	57.70 FL	*- FL
27	1		*AIR CON FAN COWLING	Cracked	125.00 FL	*125.00 FL
28	1		*AIR CON FAN MOTOR	Not Necessary	295.00 FL	*- FL
29	1		*RADIATOR	Dented	1,250.60 FL	*1,250.60 FL
30	2		*RADIATOR TOP BRACKET	Not Necessary	21.00 FL	*- FL
31	1		*RADIATOR FAN COWLING	Cracked	126.00 FL	*126.00 FL
32	1		*RADIATOR FAN MOTOR	Not Necessary	298.40 FL	*- FL
33	1		*RADIATOR FAN BLADE	Not Necessary	60.70 FL	*- FL
34	1		*RADIATOR SPARE TANK	Not Necessary	62.90 FL	*- FL
35	1		*WIPER TANK	Not Necessary	75.20 FL	*- FL
36	1		*WIPER TANK MOTOR	Not Necessary	65.40 FL	*- FL
37	1		*AIR CON SUCTION PIPE	Not Necessary	205.30 FL	*- FL
38	1		*AIR CON DISCHARGE PIPE	Not Necessary	210.40 FL	*- FL
39	1		*AIR CON LIQUID PIPE	Not Necessary	195.50 FL	*- FL
40	2		*HORN	Damaged	114.40 FL	*114.40 FL
41	1		*FRONT LOWER ARM	N/S Bent	798.40 FL	*399.20 FL
42	1		*FRONT KNUCKLE ARM	N/S Damaged	900.60 FL	*450.30 FL
43	1		*FRONT SHOCK ABSORBER	N/S Bent	729.20 FL	*389.60 FL
44	1		*FRONT WHEEL HUB C/W BEARING	N/S Damaged	387.00 FL	*193.50 FL
45	1		*STEERING CROSS MEMBER	Bent	954.20 FL	*954.20 FL
46	1		*STEERING RACK & PINION	Not Necessary	1,750.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*FRONT ANTI ROLL BAR LINKAGE	Not Necessary	136.40 FL	*- FL
48	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*30.00 FS
49	1		*FRONT NUMBER PLATE HOLDER	Missing	30.00 FS	*30.00 FS
50	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
51	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
52	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
53	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
54	2		*SET AIR CON CONDENSER SIDE GUIDE	Necessary	20.00 FS	*20.00 FS
55	1		*SET ENGINE UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
56	1		*FRONT TYRE	N/S Punctured	560.00 FS	*200.00 FS
57	1		*FRONT WHEEL RIM	N/S Cut	1,400.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,697.70	13,335.00
- List Item Discount on L Items 20.00/20.00% (\$)	3,697.54	2,495.00
Total Parts (\$)	17,000.16	10,840.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	WIRING CHECK	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	50.00
5	TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS	New	120.00	60.00
6	TO REMOVE AND REFIT RADIATOR	New	120.00	60.00
7	TO REMOVE FRONT UNDERCARRIAGE	New	750.00	350.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
9	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			3,850.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >