

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21006917/Vuce2 Ref: 8 SHENTON WAY #24-01 AXA Date: 05/07/2021 **TOWERSINGAPORE 068811** ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJP 7064S FBK 2401G Veh. Inspected Policy No. GA565086 Coverage (\$) 0.00 Claim No. S1M03C6E Excess (\$) 0.00 **Assign Date LOH CYNTHIA** 22/06/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA 400X M Make & Model 399 C.C 2015 HIDDEN Engine No. Year of Reg. NC471005762 **BLACK** Chassis No. Colour Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 120/60 R17 PIRELLI 5 mm L/H Front Tyre mm 120/60 R17 **PIRELLI** R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. 5. **General Information** 18/06/2021 22/06/2021 (05:00 PM) Inspect Date / Time Accident Date S1 MOTORING Survey held at BLK 3006 UBI ROAD 1 #01-366 SINGAPORE 408700 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000

Report Ref No. CS3/ASM21006917/Vuce2

Estimate Days of Repair

Inspected By

5b.

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days